



0015

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*File*

*su*

007/034

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

### INSPECTION REPORT

INSPECTION DATE & TIME: April 28, 1988  
10:15 a.m. to 11:30 a.m.

Permittee and/or Operators Name: Soldier Creek Coal Co.  
Business Address: P. O. Box I Price, Utah 84501  
Mine Name: Banning Siding Loadout Permit Number: ACT/007/034  
Type of Mining Activity: Underground Surface Other XX  
County: Carbon State Utah  
Company Official (s): Chris Allen  
State Official(s): Daron Haddock  
Partial: XX Complete:          Date of Last Inspection: April 18, 1988  
Weather Conditions: Cloudy, mild  
Acreage: Permitted 36 Disturbed 25.6 Regraded          Seeded          Bonded           
Enforcement Action: Terminated NOV N-88-13-1-1

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( X )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( X )	( )	( )	( X )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION April 28, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The main reason for this inspection was to check on the abatement work for NOV 88-13-1-1. The site is mostly dry with only a little water puddled in some of the larger depressions.

4d. SEDIMENT CONTROL MEASURES:

NOV 88-13-1-1 was terminated because the required sediment control structures have been installed at the site. Larger silt fence structures have been placed on either side of the road at the south end of the property. The fence appeared to be anchored securely and should treat any expected flow.

Straw bales have also been ordered and will be installed along the drainage (some inside the property fence) when they arrive.

4f. EFFLUENT LIMITATIONS:

A pipeline is being installed which will discharge water from under the grizzly to an unnamed wash. This water will be sampled according to the operator's NPDES permit and a map is being submitted showing the point of discharge.

16. ROAD DRAINAGE CONTROLS:

The two large culverts on the main haul road have been cleaned. A backhoe was cleaning the outlet ditches today, which will allow for better flow and keep them from becoming silted in. Riprap will be placed along the outlets of the culverts.

Copy of this Report:

Mailed to: Chris Allen, SCCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron Haddock #28 Date: April 29, 1988