0027

SCL

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/034

Inspection Date 1-25-88

Permittee/Operator Name Soldier Creek Coal Company

Business Address PO Box I

City Price, UT 84501 State _____ Zip _____

Mine Banning Siding ☐ Surface ☐ Underground ☑ Other

County Carbon State Utah

Company Official(s) Chris Allen

State Official(s) Holland Shepherd

Time of inspection 2:00 ☐ a.m. ☑ p.m. to 2:30 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 12-17-87 Weather conditions clear, sunny, snow on ground

Acreage ~~25~~ 36 ☐ Permitted ~~25~~ 21 ☐ Disturbed 0 ☐ Regraded 0 ☐ Seeded n/a ☐ Bonded

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☑
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/034

Inspection Date 12-25-88

Please number comments to correspond with topics on previous page.

General Comments:

Because of a death/accident which had occurred on site just a few minutes before my arrival, the operator requested that I not go on site, were the accident had happened.

I restricted this inspection to the haul road, entering the site and associated signs and markers.

16. Road Drainage Controls:

Drainage controls associated with the haul road were functioning adequately. Mr. Allen and I spoke again about minor maintenance to be performed at the outlet of culvert # 1 on the haul road.

Copy of report mailed to Chris Allen (SCCC) Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature [signature] 2-2-88 No. 9

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE