

0010

Document Information Form

Mine Number: C/007/034

File Name: Incoming

To: DOGM

From:

Person Rade H Orell

Company United States Department of the Interior

Date Sent: June 23, 1989

Explanation:

Reclamation and Enforcement

TEN-DAY NOTICE

cc:

File in: C/007, 034, Incoming

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

Orig: mine file #7
C S. L. W. L. Braxton, Pfo

RECEIVED
JUN 23 1989

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Originating Office: Albuquerque Field Office
625 Silver SW Suite 310
Albuquerque, New Mexico 87102
Telephone Number: 505-766-1486

DIVISION OF OIL, GAS & MINING - 02 - 107 - 4 TV 2

Ten-Day Notice to the State of Utah, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal inspection on 6-13-89 (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Soldier Creek Coal Company County: _____
(Or Operator if No Permit)
Mailing Address: P.O. Box 1, Price, Utah
Permit Number: 001/034 Mine Name: Banning Sidings
 Surface
 Underground
 Other load out

NATURE OF VIOLATION AND LOCATION: ^① Failure to maintain records in accordance with the requirements of the regulations. - NPDES Permit Modification for sediment Prod

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 840.14

NATURE OF VIOLATION AND LOCATION: ^② Failure to obtain a valid permit prior to engaging in or carrying out underground coal mining activities. - The revegetation test plot, the east, north +

Northwest side of
Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: the load out pad/coal outside the disturbed/permit area

Section of State Law Condition believed to

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No 0010 Date 6-23-89
In C/ 007, 034, Incoming
For additional information

Remarks or Recommendations: Issued from direction from management

Date of Notice: 21 June 1989
Cert P 965798853

Signature of Authorized Rep.: Paul H. Orell
Print Name and ID: Paul H. Orell #107

Orig: mine file #7
C S. L. Wray, L. Braxton, Pfo

RECEIVED
JUN 23 1989

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Originating Office:
Albuquerque Field Office
625 Silver SW Suite 310
Albuquerque, New Mexico 87102
Telephone Number: 505-766-1486

DIVISION OF
Oil, Gas & Mining - 02 - 107 - 4 TV 2

Ten-Day Notice to the State of Utah, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal inspection on 6-13-89 (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Soldier Creek Coal Company County: _____
(Or Operator if No Permit)
Mailing Address: P.O. Box 1, Price, Utah
Permit Number: 001/034 Mine Name: Banning Sidings
 Surface
 Underground
 Other load out

NATURE OF VIOLATION AND LOCATION: ^① failure to maintain records in accordance with the requirements of the regulations. - NPDES Permit modification for sediment Prod

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 840.14

NATURE OF VIOLATION AND LOCATION: ^② Failure to obtain a valid permit prior to engaging in or carrying out underground coal mining activities. - The revegetation test plot, the east, north +

Northwest side of Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: the load out pad/coal outside the disturbed/permit area

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 700.5 UMC 771.11

Remarks or Recommendations: Issued from the AFO per direction from management

Date of Notice: 21 June 1989
Cert: P 965798853

Signature of Authorized Rep.: Rade H. Orell
Print Name and ID: Rade H. Orell #107