

0008



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

DR #  
Joh

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

PERMIT NO.: ACT/007/034

Inspection Date: August 28, 1990

Permittee and/or Operators Name: Soldier Creek Coal Company  
Business Address: P.O. Box I  
City: Price State: Utah Zip: 84501  
Mine Name: Banning Siding Loadout  
County: Carbon State: Utah  
Type of Mining Activity: Underground Surface Other XX  
Company Official (s): Dave Spillman  
State Officials (s): Johnny Pappas and Bill Malencik  
Time of Inspection: 12:30 ( ) a.m. (X) p.m. to 2:00 ( ) a.m. (X) p.m.  
Partial XX Complete: \_\_\_\_\_ Date of Last Inspection: July 5, 1990  
Weather Conditions: Warm  
Acreage: Permitted 36.83 Disturbed 26.35 Regraded \_\_\_\_\_ Seeded \_\_\_\_\_  
Bonded 21.4  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/034 INSPECTION DATE August 28, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

The identification signs need to have the permit number changed from PRO/007/034 to ACT/007/034.

4. HYDROLOGIC BALANCE:

c. Sediment Ponds and Impoundments:

The sediment pond is in good condition with only a small amount of water covering the bottom.

d. Other Sediment Control Measures:

The silt fences appear to be in good working condition with no apparent shortcircuiting.

Berms throughout the site are in good working condition.

Copy of report:

Mailed to: Dave Spillman (SCCC)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO



Inspectors Signature and Number: Johnny Pappas #37 Date: 8/29/90