0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/034
Inspection Date June 13, 1990

Permittee/Operator Name Soldier Creek Coal Co. / Savage Coal Serv.
Business Address P.O. Box I
City Price State Utah Zip 84501
Mine Banning Siding Loadout ☐ Surface ☐ Underground ☒ Other
County Carbon State Utah
Company Official(s) Dave Spillman
State Official(s) Daron Haddock, Johnny Pappas
Time of inspection 9:40 ☒ a.m. ☐ p.m. to 3:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection May 23, 1990 Weather conditions Sunny, Mild
Acreage 36 ☐ Permitted 26.1 ☐ Disturbed ☐ Regraded ☐ Seeded 21.4 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☒	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☒
f Effluent limitations	☒	☐	☐	☒
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/034

Inspection Date June 13, 1990

Please number comments to correspond with topics on previous page.

1. Permits: The state permit for the Banning loadout was issued on Oct 24, 1988 and expires Oct 25, 1993. The bonding & insurance documents were checked and found to be in order. The approved plan has provisions for expanding the stacking & reclaim facilities on the site. At this time the operator is considering going ahead with the expansion. An additional train loading bin is part of the plan. Any disturbance outside of the approved disturbed area will require prior approval from the Division.

2. Signs & Markers: A wire on the fence at the entrance to the property has broken. This has caused the ID sign to hang down. The operator will see that this wire is repaired.

4C. Sediment Ponds & Impoundments: The operator has conducted quarterly pond inspections with the last one done on March 7, 1990. No problems were noted.

4d. Other Sediment control measures: Most run off from the site is controlled by gravel covered berms.

Copy of report mailed to

Copy of report given to

Inspector's signature Dawn R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/034

Inspection Date June 13, 1990

Please number comments to correspond with topics on previous page.

4d continued: These berms are in good condition however there are a couple of locations where sediment has accumulated on the inside of the berm. This sediment should be cleaned to maintain the effectiveness of the berm. The silt fences at the site are in good repair.
4e. Surface + groundwater monitoring: Coal Sampling is done in lieu of the water monitoring. Samples were analyzed quarterly through 1989. All required parameters were checked.
4f. Effluent Limitations: The operators Discharge Monitoring reports indicate no discharge from the site for the last year.
12+13: Backfilling + grading + revegetation: The area disturbed during the recent construction of the power substation has been regraded + seeded. At this point vegetation has not germinated. (Probably due to extreme dry conditions.)
16b. Road drainage controls: The road culverts are clear + funtioning well.
18. Support facilities + utility installations: The operator will check on the disposition of the small white "Wendon" shed at the south end of the property. It should be removed if no longer required for the loading operation.

Copy of report mailed to Brian Smith (OSM) Dave Spillman (SCCC) PFO

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE