

0001



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DR7
Gak

INSPECTION REPORT

Permit No. ACT/007/034 Inspection Date: December 17, 1991
 Permittee and/or Operators Name: Soldier Creek Coal Co./Savage
 Business Address: P.O. Box I City: Price State: Utah Zip: 84101
 Mine Name: Banning Loadout County: Carbon State: Utah
 Type of Mining Activity: Underground Surface Other XX
 Company Officials: Johnny Pappas State Officials: Steve Demczak
 Time of Inspection: 9:00 a.m. - 2:00 p.m. Partial Complete: X
 Acreage: Permitted 36 Disturbed 26.1 Regraded 0
 Seeded 0 Bonded 21.4 Date of Last Inspection: November 12, 1991
 Weather Conditions: Cool, Teens Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()
19. AVS Check	(X)	()	()	(X)

Permit No. ACT/007/034 Inspection Date December 17, 1991(Comments are Numbered to Correspond with Topics Listed Above)1. Permits -

- a. Reviewed the pond inspection reports for 3rd quarter which were taken on September 9, 1991. The reports indicated that the pond was 1 foot away from discharging. A storm event had taken place on September 7, 1991.
- b. Reviewed and examined the ground water sampling data for Banning Loadout with the required parameters. All parameters were analyzed.
- c. Reviewed sediment pond design and construction drawings.
- d. After reviewing the annual reports on sediment ponds, additional detail was shown to be lacking. This detail would be helpful for clarification.

4c. Sediment Ponds and Impoundments -

The pond was inspected and contained a small amount of water and no performance standards were violated.


13. Revegetation -

The new test plot was examined and each specie is labeled.

19. AVS Check -

An AVS check was made with no changes at this time. The company is up for sale.

Copy of report:

Mailed to: Soldier Creek Coal Co./SavageMailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: January 2, 1992Inspector's Signature and Number: 
Stephen J. Demczak #39