



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*Handwritten initials/signature*

Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: 10/18/91  
12:30 P.M.-1:30 P.M.

Permittee and/or Operator's Name: Soldier Creek Coal Co., Savage Coal Services Corp.  
Business Address: Permittee: P. O. Box I, Price, Utah 84501; Operator: P. O. Box 587, Wellington, Utah 84542 Mine Name: Banning Loadout Permit Number: ACT/007/034  
Type of Mining Activity: Underground Surface Other X  
County: Carbon Company Official(s): Tom Paluso State Officials(s): Paul Baker Federal Official(s): None Partial: X Complete:    Date of last Inspection: 9/23/91  
Weather Conditions: Clear, 70's  
Acreage: Permitted-36 Disturbed-21.4 Regraded-    Seeded-    Bonded-21.4  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: 10/18/91

(Comments are Numbered to Correspond with Topics Listed Above)

### 1. Permits

I conducted an AVS check, and there are no changes. The permittee is Soldier Creek Coal Co., a subsidiary of Sunedco Coal Co. which is a subsidiary of Sun Co. The operator is Savage Coal Services. Tom Paluso indicated that Soldier Creek Coal Co. is for sale and that the sale should be completed next year.

I discussed the test plot design briefly with Johnny Pappas. He has discussed the design with consultants and is in the process of preparing the amendment submittal in accordance with the Division Order issued after the mid-term review site visit.

### 4.b. Diversions

We checked the berms, silt fences, and straw bales on the road and around the property. All appeared to be in good repair.

### 4.c. Sediment Pond


The erosion noted in the August 6, 1991, inspection report had been repaired.

Copy of this Report:

Mailed to: Soldier Creek Coal, Bernie Freeman (OSM)

Given to: Daron Haddock and Joe Helfrich (DOGM)

Inspector's Signature: \_\_\_\_\_



Paul B. Baker #41 Date: 10/18/91