

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

John Pappas

INSPECTION REPORT

INSPECTION DATE & TIME: 7/25/91
09:30 am- 10:30 am

Permittee and/or Operator's Name: Soldier Creak Coal Co/Savage
Business Address: P.O. Box I Price, Utah, 84501 Phone: 637-6360
Mine Name: Banning Siding Load Out Permit Number: Act 007/034
Type of Mining Activity: Underground Surface Other x
County: Carbon Company Official(s): Johnny Pappas
State Officials(s): Sharon Falvey
Federal Official(s): none
Partial: x Complete Date of last Inspection: 06/14/91
Weather Conditions: Calm, Overcast
Acreage: Permitted 36 Disturbed 21.4 Regraded Seeded
Bonded 21.4 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	(x)	()	()	(x)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(x)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	(x)	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: 7/25/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

A revised surface facilities map was received by the Division on July 18, 1991. The map was submitted in response to Steve Demczak's request to correct the facilities map during the June 14, 1991 inspection.

2. SIGNS AND MARKERS

In the April 24, 1991 inspection, inspector Priscilla Burton, indicated that the operator had agreed to repaint the revegetation reference area with orange Paint. Although the area is identified with stakes, the operator has not yet repainted the stakes as agreed. The operator was reminded of the previous agreement. The stakes should be repainted by the next inspection.

4. HYDROLOGIC BALANCE

d. OTHER SEDIMENT CONTROL MEASURES

Soldier Creek has installed the snow fence at the North end of the Permit boundary to minimize windblown coal transport off of the permit area.

Copy of this Report:

Mailed to: Brian Smith (OSM), Johnny Pappus SC3

Given to: Joe Helfrich and Daron Haddock DOGM

Inspector's Signature & Number: Shawn K. Falvey #38 Date: 2/25/91