

0017



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

PERMIT NO.: ACT/007/034  
Inspection Date: January 24, 1991

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage  
Business Address: P.O. Box I  
City: Price State: Utah Zip: 84501  
Mine Name: Banning Load Out  
County: Carbon State: Utah  
Type of Mining Activity: Underground  Surface  Other   
Company Official (s): Johnny Pappas  
State Officials (s): Stephen J. Demczak  
Time of Inspection: 12:01 ( ) a.m. (  ) p.m. to 2:00 ( ) a.m. (  ) p.m.  
Partial  Complete:  Date of Last Inspection: Dec. 31, 1990  
Weather Conditions: Clear/Cool  
Acreage: Permitted 36 Disturbed 26.1 Regraded  Seeded   
Bonded 21.4 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( <input checked="" type="checkbox"/> )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
d. OTHER SEDIMENT CONTROL MEASURES	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/034 INSPECTION DATE January 24, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

Identification signs were located on both gates entering the property. The undisturbed markers are located on the fence surrounding the loadout facilities.

4. HYDROLOGIC BALANCE:

c. Sediment Ponds And Impoundments:

Ponds were inspected and no erosion was observed. The ponds contained a small amount of water.

d. Other Sediment Control Measures:

All silt fences were functional.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES:

Several head of antelope were observed grazing just beyond the undisturbed markers.

13. REVEGETATION:

The test plot contains very little vegetative growth.

Copy of report:

Mailed to: Soldier Creek Coal Co./Savage Coal  
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)  
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39  
Date: 1/30/91

