

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

OP 71
gch

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: August 19, 1992
7:30 am. - 8:00 am.

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage
Business Address: P.O. Box I, Price, Utah 84101
Mine Name: Banning Load Out Permit Number: Act/007/034
Type of Mining Activity: Underground Surface Other X
County: Carbon Company Official (s): Tom Paluso
State Official(s): Sharon Falvey
Partial: x Complete: Date of Last Inspection: 7/7/1992
Weather Conditions: Clear, Moderate
Acreage: Permitted 36 Disturbed 26.1 Regraded 0 Seeded 0
Bonded 21.4 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	(x)
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(x)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(x)	()	()	(x)
14. SUBSIDENCE CONTROL	()	()	(x)	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()
19. AVS INFORMATION	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: 84/19/92

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

c. SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was dry. The last report indicated rills on the pond inslope were corrected. Some rills were present during this inspection. They do not pose a hazard to the pond stability at this time. It appears the nature of the soils at the pond are conducive to forming rills. The operator should be aware that frequent attention may be necessary to minimize rill formation at the pond.

d. OTHER SEDIMENT CONTROL MEASURES

The silt fence adjacent to the test plot was in need of minor maintenance. Wire from portions of the fence have loosened from the roof bolts used to attach and secure the silt fence. The operator should adjust the wires to assure proper function of the silt fence.

e. SURFACE AND GROUNDWATER MONITORING

13. REVEGETATION

The test plot is presently heavily vegetated with weeds. The grasses that established earlier in the season are visible under the weedy species.

Copy of this Report:

Mailed to: Brian Smith (OSM)

Given to: Daron Haddock, Rick Summers, Joe Helfrich (DOGM)

Inspector's Signature: Sharon Falvey #38 Date: 8/20/92