



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

June 30, 2015

Kirt Tatton, General Manager
Canyon Fuel Company, LLC
P.O. Box 1029
Wellington, Utah 84542

Subject: 2014 Annual Report Review Completion, Banning Loadout, C/007/0034, Task ID #4851

Dear Mr. Tatton:

The Division staff has completed the review of the 2014 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on June 30, 2015.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5350.

Sincerely,

Steve Christensen
Permit Supervisor

SKC/sqs
Enclosure
O:\007034.BAN\WG4851 ANNUAL REPORT\ReviewCompletionLetter.doc



Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Canyon Fuel Company, LLC	Mine Name	Banning Loadout
Permit Number	C/007/0034	Permit expiration Date	10-24-18
Operator Name	Same	Phone Number	+1 (435) 637-6360
Mailing Address	PO Box 1029	Email	dspillman@bowieresources.com
City	Wellington		
State	Utah	Zip Code	84542

DOGGM File Location or Annual Report Location

Excess Spoil Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Refuse Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Attached
Other:		

OPERATOR COMMENTS

REVIEWER COMMENTS

Met Requirements Did Not meet Requirements

The General Information submitted with the 2014 Annual Report information is complete and adequate. The current permit issued by the State of Utah / DOGM remains in effect through October 24, 2018. All permit information for the Banning site is on file at the Permittees Dugout Canyon Mine. The site remains in temporary cessation status. All surface facilities have been reclaimed with the exception of the truck dump grizzly and the asphalted access road.

The Permittee submitted quarterly impoundment inspection reports for all 4 quarters of 2014. The 1st Quarter and 4th Quarter inspections were P.E. certified by Mr. David G. Spillman, Utah registered professional engineer and Manager of Technical Services for the Permittee. There were no signs of instability, structural weakness, or other hazardous conditions reported during any of the quarterly inspections, either by Mr. Spillman, or his qualified individual, Mr. John Hannert. The sediment level in the pond reported during the 4th

Quarter inspection was reported as being well below the 60% cleanout elevation @ 5,486.6 feet. This pond is incised. The pond has never discharged; it was noted that the pond did not contain any impounded water during any of the 2014 quarterly inspections (PHH, 3/31/2015).

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

N/A

Reviewer Comments