


## Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538

(copy)  
ACT/007/035 #2

November 20, 1997

Department of Environmental Quality  
Division of Water Quality  
288 North 1460 West  
P. O. Box 144870  
Salt Lake City, Utah 84114-4870



Attention: Mr. Michael Herkimer

Subject: November, 1997, UPDES Compliance Report  
October, 1997, Monitoring Period  
UPDES Permit No. UT0024759  
Discharge Monitoring Report Forms  
Sunnyside Cogeneration Facility, Sunnyside, Utah

Dear Mr. Herkimer:

This letter summarizes the UPDES-permit field activities at the Sunnyside Cogeneration Facility during October, 1997. Rusty Netz, the Environmental Technician for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the October, 1997, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Field Data Sheets are included in Attachment B.

If you have any questions concerning this report, please contact Rusty Netz, Environmental Technician, at (801) 888-4476.

Sincerely,

Harold C. Sallas  
General Manager

HCS/lls

Enclosures:

Attachment A: Monitoring Report Forms  
Attachment B: Field Data Sheets

c.c. Doug Burnham, Babcock & Wilcox (w/o attachments)  
Robert Evans, NRG Energy, Inc. (w/o attachments)  
Rusty Netz, Sunnyside Operations Associates  
Ken Wyatt, Division of Oil, Gas and Mining  
SCA Plant file