DOM

STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining

3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: June 1, 1998
Time: 8 : 30 ☑am ☐pm to 2 : 00 ☐am ☑pm
Date of Last Inspection: 5/4/98

Mine Name: Sunnyside Refuse County: Carbon Permit Number: Act 007/035
Permittee and/or Operator's Name: Sunnyside Cogeneration Associates
Business Address: P.O. Box 10, East Carbon
Type of Mining Activity: ☐ Underground ☑ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): Rusty Netz
Federal Official(s): N/A
Weather Conditions: Clear / Temp Upper 60°s / Dry Mine Site
Existing Acreage: Permitted-310 Disturbed-202 Regraded-____ Seeded-____ Bonded-202
Increased/Decreased: Permitted-____ Disturbed-____ Regraded-____ Seeded-____ Bonded-____
Status: ☐ Exploration / ☑ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☑	☐	☑	☐
2. SIGNS AND MARKERS	☑	☐	☑	☐
3. TOPSOIL	☑	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☑	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☐	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☐	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☐	☐	☐
5. EXPLOSIVES	☐	☑	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☑	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☐	☐	☐	☐
8. NONCOAL WASTE	☑	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☑	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☑	☐	☑	☐
b. DRAINAGE CONTROLS	☑	☐	☑	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☐	☐	☐	☐
19. AVS CHECK (4th Quarter-April, May, June)____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. 6/1/98

Inspection Date Act 007/035

Please number comments to correspond with topics on previous page.

General Comments. A partial inspection was completed of the surface mine and the tipple area/processing plant.

Permit. The Division letter of 5/27/98 to Mr. Sallas the mine general manager highlighted the following:

- Surety bond $1,900,000.00
- AVS recommendation. Conditional issue. Mr. T.H Black.
- Savage Industries Inc is no longer the operator, but is nothing more than the permittees contractor.
- T.A was submitted to the operator
- Followup action required: revise MRP by July 10, 1998

I.D. Sign. The I.D sign was down. It appears a vehicle was the causative factor. The sign is locate in a turn around area adjacent to the road. Mr Netz took the sign back to the shop for maintenance before again reinstalling the sign.

Diversion. The "Spring" diversion project has been completed. Many ditches were regraded and berms beefed up where necessary.

Roads. The roads were recently watered for dust suppression. Further, most of the road ditches were regraded.

Copy of report mailed to SCA/Netz; OSM/Austin; Doom/Helfrich

Copy of report given to Price Field Office

Inspector's signature Tim J. Malecik No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

6/5/98

DOGM/IR-2

an equal opportunity employer

11/86 001049