


Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538

March 30, 1999

Department of Environmental Quality
 Division of Water Quality
 288 North 1460 West
 P. O. Box 144870
 Salt Lake City, Utah 84114-4870



Attention: Mr. Michael Herkimer

ACT/007/035 #7

Subject: March 1999, UPDES Compliance Report
 February 1999, Monitoring Period
 UPDES Permit No. UT0024759
 Discharge Monitoring Report Forms
 Sunnyside Cogeneration Facility, Sunnyside, Utah

Dear Mr. Herkimer:

This letter summarizes the UPDES-permit field activities at the Sunnyside Cogeneration Facility during February 1999. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the February 1999, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Field Data Sheets are included in Attachment B.

If you have any questions concerning this report, please contact me at (435) 888-4476.

Sincerely,

Rusty Netz

Rusty Netz
 Environmental Coordinator

RN/lls

Enclosures:

Attachment A: Monitoring Report Forms
Attachment B: Field Data Sheets

c.c. Mr. Doug Burnham, Babcock & Wilcox (w/o attachments)
 Mr. Robert Evans, NRG Energy, Inc. (w/o attachments)
 Mr. Ken Wyatt, Division of Oil, Gas and Mining
 SCA Plant file