

0017

Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538

June 22, 1999

Department of Environmental Quality
Division of Water Quality
288 North 1460 West
P. O. Box 144870
Salt Lake City, Utah 84114-4870

ACT 1007/035 #7

Attention: Mr. Michael Herkimer

Subject: June 1999, UPDES Compliance Report
May 1999, Monitoring Period
UPDES Permit No. UT0024759
Discharge Monitoring Report Forms
Sunnyside Cogeneration Facility, Sunnyside, Utah

Dear Mr. Herkimer:


This letter summarizes the UPDES-permit field activities at the Sunnyside Cogeneration Facility during May 1999. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the May 1999, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Field Data Sheets are included in Attachment B.

If you have any questions concerning this report, please contact me at (435) 888-4476.

Sincerely,

Rusty Netz
Environmental Coordinator



RN/lls

Enclosures:

Attachment A: Monitoring Report Forms
Attachment B: Field Data Sheets

c.c. Mr. Doug Burnham, Babcock & Wilcox (w/o attachments)
Mr. Robert Evans, NRG Energy, Inc. (w/o attachments)
Mr. Ken Wyatt, Division of Oil, Gas and Mining
SCA Plant file