


0029

## Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538

October 15, 1999



Department of Environmental Quality  
Division of Water quality  
288 North 1460 West  
P.O. Box 144870  
Salt Lake City, Utah 84114-4870

Attention: Mr. Michael Herkimer

ACT/007/085 #7

Subject: October 1999, UPDES Compliance Report  
September 1999, Monitoring Period  
UPDES Permit No. UT0024759  
Discharge Monitoring Report Forms  
Sunnyside Cogeneration Facility, Sunnyside, Utah

Dear Mr. Herkimer:

This letter summarizes the UPDES-Permit field activities at the Sunnyside Cogeneration Facility during September 1999. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the September 1999, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Bio-Monitoring Forms are included in Attachment B. The Field Data Sheets are included in Attachment C.

If you have any questions concerning this report, please contact me at (435) 888-4476.

Sincerely,

*Rusty Netz*  
Rusty Netz  
Environmental Coordinator

RN/ta0  
Enclosures:

Attachment A: Monitoring Report Forms  
Attachment B: Bio-Monitoring Report Forms  
Attachment C: Field Data Sheets

cc: Ken Wyatt, Division of Oil, Gas and Mining  
SCA Plant file  
Rusty Netz, COSI