007/035 #6

0005

1998 Annual Report Review

Permittee: Sunnyside Cogeneration Associates
Mine Name: Sunnyside Refuse/Slurry
Permit Number: ACT/007/035
Date Report Received 3/31/99 SLO / 4/1/99 PFO

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, a copy will be filed in the Mine folder #6.

Assigned Reviewers: Peter Hess - Engineer

Section to review	Submitted Yes	No	Findings
Cover sheet	—	—	
AVS; Legal/Financial Update	—	—	
Mine Sequence Map	—	—	
Water Monitoring Data	—	—	
Precipitation & Climatological Data	—	—	
Non-Coal Waste	—	—	
* Subsidence monitoring data	—	✓	Report not required. No subsidence exists or will exist.
* Annual Impoundment Certification	✓	—	All impoundment inspections/certifications P.E. certified by Scott Carlson. All are adequate.
* Annual Overburden, Spoil, Refuse, Floor, etc.	✓	—	Sunnyside refuse pile P.E. certified by Scott Carlson. Inspection appears adequate. No Refuse analyses submitted.
Vegetation data	—	—	
Revegetation Success monitoring	—	—	