



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

INSPECTION REPORT

Partial: Complete: XXX Exploration:

Inspection Date & Time: 4/13/99 / 9:00A.M.-2:30P.M.

Date of Last Inspection: 3/18/99

Mine Name: Sunnyside Refuse/Slurry County: Carbon Permit Number: ACT/007/035

Permittee and/or Operator's Name: Sunnyside Cogeneration Associates

Business Address: P.O. Box 10, East Carbon, Utah 84520

Type of Mining Activity: Underground Surface XXX Prep. Plant Other

Company Official(s): Rusty Netz

State Officials(s): Bill Malencik Federal Official(s): None

Weather Conditions: Partly Cloudy, Windy

Existing Acreage: Permitted- 310 Disturbed- 202 Regraded- Seeded- Bonded- 202

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability 1994 Course Refuse Road)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/035

DATE OF INSPECTION: 4/13/99

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

Conducted a complete inspection of the Sunnyside Surface Mine. The inspection covered the tipple, upper and lower permitted areas.

2. SIGNS AND MARKERS

The mine has installed a mine ID sign at the interface of each public access road. Other signs observed included MSHA refuse sign and topsoil signs. The existing disturbed boundary and permit boundary have been posted.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Disturbed and undisturbed diversions are shown on plate 7-6, individual designed diversions are on Appendix 7-3. The disturbed diversions include culverts, berms, and ditches.

A sampling of key diversions during the inspection did not uncover any maintenance problems. During plant maintenance, the diversions will be regraded where necessary.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The disturbed area contains 11 impoundments, of which seven are sediment ponds. There are four slurry approved impoundments. Slurry cell one and two are non-MSHA impoundments. The east and west slurry cells are MSHA impoundments. All slurry cells are inactive. This occurred when the Sunnyside Mine closed and no longer washed coal in 1994. Furthermore, the slurry ditch has just been reclaimed in 1999 and no slurry will be conveyed to the slurry cells. The sediment ponds and slurry cells were inspected and reports reduced to writing.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

There are three small areas where designed silt fences and/or vegetation has been approved by the Division to provide sediment control.

Area 1 - South of the clear water pond, vegetation is the treatment.

Area 2 - South of the reclaimed coarse refuse road, silt fences and vegetation are the treatment.

Area 3 - Noise Canyon Railroad culvert, adjacent up-slope, silt fence, and vegetation provides the treatment.

There are other soil and sediment control devices including silt fences; however, these are redundant control measures. All such areas drain into approved sediment ponds.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/035

DATE OF INSPECTION: 4/13/99

(Comments are Numbered to Correspond with Topics Listed Above)

6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES

The permittee has an approved site to store spoil and tipple processing waste.

This site was approved so that coal waste, embankment material would be stored on the spoil pile and not on the refuse pile. Spoil material was being stored in lifts on the spoil pile.

A sizeable amount of rock is currently stored on the outslope. This was briefly discussed with Mr. Netz. While the plan does not require, it would be easier to reclaim the spoil outslope after each lift is completed. Mr. Netz said he and Scott Carlson would look into the matter on his next trip to Sunnyside.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee is currently mining the west slurry cell and contiguous refuse pile. No mining has started on the east slurry cell.

8. NONCOAL WASTE

Currently, there is not an active non-coal waste storage area. The non-coal waste is currently stored in a dumpster.

16B. ROADS: DRAINAGE CONTROLS

All roads were recently graded including several road ditches adjacent to the haul roads. Requested the permittee to re-define and maintain the road ditch adjacent to pasture pond inlet.

20. AIR QUALITY PERMIT

An air quality order is on file at the mine site. The order requires the permittee to water roads in order to control fugitive dust. The haul roads were watered during the inspection.

21. BONDING AND INSURANCE

Insurance was recently renewed and covers the period 3/25/99 to 3/25/00.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Rusty Netz (Cogen) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: April 14, 1999

Inspector's Signature: *Wm. J. Malencik* #26
Wm. J. Malencik