



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

May 17, 2000

Department of Environmental Quality
 Division of Water Quality
 288 North 1460 West
 P.O. Box 144870
 Salt Lake City, Utah 84114-4870

Attention: Mr. Michael Herkimer

Subject: May 2000, UPDES Compliance Report
 April 2000, Monitoring Period
 UPDES Permit No. UT0024759
 Discharge Monitoring Report Forms
 Sunnyside Cogeneration Facility, Sunnyside, Utah

Franking
Ken
Hydro
 INCOMING
 ACT/007/035

Dear Mr. Herkimer:

This letter summarizes the UPDES-Permit field activities at the Sunnyside Cogeneration Facility during April 2000. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the April 2000, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A.. The Field Data Sheets are included in Attachment B.

If you have any questions concerning this report, please contact Rusty Netz at (435) 888-4476.

Sincerely,

Agent for
 Sunnyside Cogeneration Associates

Randy Scott
 Plant Manager

RN/ta
 Enclosures:

Attachment A: Monitoring Report Forms
Attachment B: Field Data Sheets

cc: Ken Wyatt, Division of Oil, Gas and Mining
 SCA Plant file
 Rusty Netz, COSI

RECEIVED

MAY 22 2000

DIVISION OF
 OIL, GAS AND MINING