



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Handwritten signature/initials

INSPECTION REPORT

Partial XXX Complete Exploration
Inspection Date: 02/25/2002 / Time: 10:00 - 12:00
Date of Last Inspection: 01/30/2002

Mine Name: Sunnyside Cogeneration Associates County: Carbon Permit Number: C/007/035
Permittee and/or Operator's Name: Plateau Mining Corporation
Business Address: P.O. Box 10, East Carbon, Utah 84520
Company Official(s): Rusty Netz
State Official(s): Karl R. Houskeeper Federal Official(s): None
Weather Conditions: Clear & Cold, Temp 10 - 20°F
Type of Mining Activity: Underground Surface XXX Prep Plant Other
Existing Acreage: Permitted 310 Disturbed 202 Regraded Seeded
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, etc.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/035

DATE OF INSPECTION: 02/25/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

Observed the ID sign adjacent to the tipple. The disturbed markers were checked and no problems were noted. The MSHA refuse & impoundment signs were observed. All of the signs and markers meet the coal rules.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee notified the Division by letter dated December 5, 2001 that the fourth quarter water sampling and UPDES DMR data was submitted to the EDI web site. Fourth quarter information was checked on the web site. Water monitoring is current.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile appeared stable with no visible hazards. No smokers were present at the time of the inspection. The refuse pile serves as a fuel source for the power plant that sits adjacent to the permit area. The pile is being lowered in lifts by a loader and truck.

Inspector's Signature: _____

Karl R. Houskeeper

#49

Date: February 26, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Rusty Netz, Cogen
Price Field office

O:\007035.SRS\Compliance\2002\p_0225.doc