

INSPECTION REPORT

Partial XXX Complete Exploration
 Inspection Date: 03/20/2003/ Time: 9:30 – 11:30
 Date of Last Inspection: 02/18/2003

Mine Name: Sunnyside Refuse/Slurry County: Carbon Permit Number: C/007/035
 Permittee and/or Operator's Name: Sunnyside Cogeneration Associates
 Business Address: P.O. Box 10, East Carbon, Utah 84520
 Company Official(s): Rusty Netz
 State Official(s): Karl R. Houskeeper Federal Official(s): None
 Weather Conditions: Partly Cloudy, Temp 42°F
 Type of Mining Activity: Underground Surface XXX Prep Plant Other
 Existing Acreage: Permitted 310 Disturbed 202 Regraded Seeded
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2.	SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.	TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c.	OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d.	WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e.	EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5.	EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8.	NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.	SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11.	CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.	BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13.	REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14.	SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15.	CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.	DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17.	OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19.	AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20.	AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21.	BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/035

DATE OF INSPECTION: 03/20/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

The mine ID sign located adjacent to the tiple contained the necessary information. The MSHA Refuse and Impoundment signs were checked during the inspection. All other signs and markers observed during the inspection comply with the coal rules.

3. TOPSOIL

The topsoil pile located near excess spoil pile #2 has a berm that has been damaged by a piece of equipment. The berm is still functional but has been substantially weakened. Arrangements were made before the end of the inspection to have the berm repaired immediately.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring for the first quarter of 2003 is in the final stage of completion this week. Fourth quarter 2002 water monitoring is in the EDI website and is uploaded.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Inspected the refuse pile. No visible hazards were noted. Refuse is being extracted at several different sites from the refuse pile and the decommissioned slurry cell. Several sites are being utilized depending on the quality requirements and blend ratios of the power plant.

Refuse material from the Star Point Refuse Pile is still being utilized as a fuel source for the power plant. A temporary storage area for the Star Point Refuse is established within the disturbed area. Weight tickets are being used to determine the amount of material hauled on a monthly basis from the Star Point Refuse Pile to the Sunnyside Cogeneration site.

An alternate fuel source is also being hauled in and stock piled in the disturbed area east of the Star Point temporary storage site. Utilizing this material as a fuel source is authorized as a remediation of the material. Weight tickets from trucks determine the amount of material received on a monthly basis. This information is tracked and provided to the Division for review.

Inspector's Signature: _____ Date: March 21, 2003
Karl R. Houskeeper #49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Randy Scott, Cogen
Price Field office

O:\007035.SRS\Compliance\2003\p_0320.doc