



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Company, Name/Title. Row 1: Rusty Netz, Environmental Coordinator. Row 2: OGM, Karl Houskeeper, Environmental Scientist III.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number (C0070035), Inspection Type (COMPLETE), Inspection Date (Wednesday, November 16, 2005), Start Date/Time (11/16/2005 12:00:00 PM), End Date/Time (11/16/2005 4:00:00 PM), Last Inspection (Thursday, October 20, 2005).

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 40 Deg. F

InspectionID Report Number: 785

Accepted by: pgrubaug
11/28/2005

Permittee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES
Site: SUNNYSIDE REFUSE & SLURRY
Address: PO BOX 159, SUNNYSIDE UT 84539
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Rows: 310.00 Total Permitted, 202.00 Total Disturbed, Phase I, Phase II, Phase III.

Mineral Ownership

- Federal, State, County, Fee (checked), Other

Types of Operations

- Underground, Surface, Loadout, Processing, Reprocessing (checked)

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Permit actions: Task ID #2332 Fertilizer Removal was withdrawn.

Inspector's Signature

Date Wednesday, November 16, 2005

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Permit actions: Task ID #2332 Fertilizer Removal was withdrawn.

The following permits were reviewed:

- Mining permit C/007/035 issued February 4, 2003 and expires February 4, 2008.
- UPDES permit #UT0024759 effective August 1, 2002 and expires midnight July 31, 2007.
- Air Quality Permit DAQO-702038-02 issued November 1, 2002, remains in effect.
- SPCC plan is only applicable to plant site which is not within the permit area.
- Certificate of Insurance effective 08/01/2005 and terminates 08/01/2006.
- Reclamation agreement is dated December 1996 and signed by both parties.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse and Impoundment signs were also checked during the inspection and contained the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Third quarter 2005 sediment pond inspections were conducted on September 20, 2005 and compiled into a report dated October 14, 2005. The reports for each pond are P.E. certified, signed, and dated.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2005 water monitoring is in the EDI website and uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for September 2005 were viewed as part of the complete inspection.

6. Disposal of Excess Spoil, Fills, Benches

The excess disposal areas were inspected on September 20, 2005 by a Registered Professional Engineer. The information from that inspection is contained in an inspection report dated October 14, 2005.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on September 20, 2005 by a Registered Professional Engineer and was compiled into a report dated October 14, 2005.

The refuse pile appeared stable with no visible hazards during the complete inspection.

19. AVS Check

The Applicant/Violator System (AVS) was checked on May 26, 2005. No violations were listed. The entity ID showed 149252 Sunnyside Holdings I, Inc., 50% ownership and 149255 Sunnyside II, LP, 50% ownership, which correlates with the information contained in the approved Mining and Reclamation Plan (MRP).

20. Air Quality Permit

DAQO-702038-02 issued November 1, 2002, remains in effect. Air Quality Permit DAQE-691-99 issued August 13, 1999 was replaced by DAQO-702038-02. The permit was modified to allow the usage of a diesel generator on the power plant site. The Air Quality Permit covers both the power plant and mine site. The power plant site is not regulated by DOGM.

21. Bonding and Insurance

A Pledge and Escrow agreement dated January 4, 2002 is in place. The escrow agency is Wells Fargo for SCA. SCA has invested \$1,747,000 in federally guaranteed Treasury Notes. The required bond amount is \$1,720,000.