



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

January 23, 2007

Pam Grubaugh-Littig

Utah Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84114

RE: Fourth Quarter 2006 Inspection Report
Sunnyside Refuse Pile C/007/035

George
C/007/0035

Dear Pam:

Please find enclosed a copy of the Fourth Quarter 2006 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas. The inspection was performed by a qualified SCA employee and certified by a professional engineer from Twin Peaks Engineering.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Michael J. Blakey
Agent For
Sunnyside Cogeneration Associates

c.c. Robert Escalante
Ramiro Garcia
Rusty Netz
Plant File

File in: C/0070035 Morning

Refer to:

- Confidential
- Shelf
- Expandable

Date For additional information

01232007

RECEIVED
JAN 29 2007
DIV. OF OIL, GAS & MINING