

0013

*Outgoing  
CA070035  
&*

**From:** Karl Houskeeper  
**To:** rnetz@emerytelcom.net  
**CC:** Angela Nance; Daron Haddock; Suzanne Steab  
**Date:** 10/5/2009 1:09 PM  
**Subject:** September 2009 Inspection Reports  
**Attachments:** SCA September 2009.pdf; SPWF September 2009.pdf

Rusty,

Attached are the SPWF and SCA September 2009 inspection Reports.

Thanks,  
Karl



**State of Utah**  
**Department of**  
**Natural Resources**

MICHAEL R. STYLER  
*Executive Director*

**Division of**  
**Oil, Gas & Mining**

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

Representatives Present During the Inspection:	
Company	Rusty Netz Environmental Coordinator
OGM	Karl Houskeeper Environmental Scientist III

# Inspection Report

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Thursday, September 17, 2009
Start Date/Time:	9/17/2009 12:00:00 PM
End Date/Time:	9/17/2009 3:30:00 PM
Last Inspection:	Wednesday, August 26, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 73 Deg. F.

InspectionID Report Number: 2138

Accepted by: jhelfric  
 9/21/2009

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**  
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**  
 Site: **SUNNYSIDE REFUSE & SLURRY**  
 Address: **ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

Current Acreages	
310.00	Total Permitted
202.00	Total Disturbed
5.50	Phase I
	Phase II
	Phase III

**Mineral Ownership**

- Federal
- State
- County
- Fee
- Other

**Types of Operations**

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: \_\_\_\_\_

*Karl Houskeeper*

Date Thursday, September 17, 2009

Karl Houskeeper, Environmental Scientist III  
 Inspector ID Number: 49

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070035  
 Inspection Type: PARTIAL  
 Inspection Date: Thursday, September 17, 2009

Inspection Continuation Sheet

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070035  
Inspection Type: PARTIAL  
Inspection Date: Thursday, September 17, 2009

**Inspection Continuation Sheet**

*Page 3 of 3*

**2. Signs and Markers**

The mine ID sign is located adjacent to the tibble on a light pole. The MSHA Refuse Pile sign was also checked during the inspection and contained the required information.

**6. Disposal of Excess Spoil, Fills, Benches**

Excess spoil pile #2 is actively receiving material.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile is being mined in lifts. The pile appeared stable. No visible hazards noted.