

**From:** Karl Houskeeper  
**To:** rnetz@emerytelcom.net  
**CC:** ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov  
**Date:** 3/28/2011 4:10 PM  
**Subject:** March 2011 Inspection Reports  
**Attachments:** SCA March 2011.pdf; SPWF March 2011.pdf

Rusty,

Attached are the March 2011 inspection reports for SCA and SPWF.

Thanks,  
Karl



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070035
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, March 15, 2011
Start Date/Time:	3/15/2011 8:00:00 AM
End Date/Time:	3/15/2011 11:00:00 AM
Last Inspection:	Thursday, February 17, 2011

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear, Temp. 43 Deg. F.

InspectionID Report Number: 2680

Accepted by: jhelfric

3/17/2011

Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**

Operator: **SUNNYSIDE COGENERATION ASSOCIATES**

Site: **SUNNYSIDE REFUSE & SLURRY**

Address: **PO BOX 159, SUNNYSIDE UT 84539**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

#### Current Acreages

323.95	<b>Total Permitted</b>
202.00	<b>Total Disturbed</b>
5.35	<b>Phase I</b>
5.35	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: \_\_\_\_\_

Date

Tuesday, March 15, 2011

Karl Houskeeper,

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.  
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## **1. Permits, Change, Transfer, Renewal, Sale**

The following permits were reviewed:

- Mining permit C/007/035 issued February 3, 2008 and expires February 4, 2013.
- UPDES permit #UT0024759 effective August 1, 2007 and expires midnight July 31, 2012.
- Air Quality Permit DAQO-702038-02 issued November 1, 2002, remains in effect.
- SPCC plan is only applicable to plant site which is not within the permit area.
- Certificate of Insurance effective 08/01/2010 and terminates 08/01/2011.
- Reclamation agreement is dated December 1996 and signed by both parties.

## **2. Signs and Markers**

The mine ID sign is located on a light pole at the entrance into the permit area.

### **4.a Hydrologic Balance: Diversions**

Several culvert inlets and outlets have tumble weeds collected around them . The weeds could incur a blockage if not removed.

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Fourth quarter 2010 sediment pond inspections were done on December 16, 2010. This inspection was also the 2010 annual inspection.

### **4.e Hydrologic Balance: Effluent Limitations**

Reviewed the January 2011 discharge monitoring reports. No discharges occurred from any of the outfalls.

## **6. Disposal of Excess Spoil, Fills, Benches**

During the fourth quarter 2010 excess disposal sites #1 & #2 were inspected on December 16, 2010.

## **7. Coal Mine Waste, Refuse Piles, Impoundments**

During the fourth quarter 2010 the refuse pile was inspected on December 16, 2010. Currently the pile appeared stable.

## **20. Air Quality Permit**

DAQ-702038-02 issued November 1, 2002, remains in effect. Air Quality Permit DAQE-691-99 issued August 13, 1999 was replaced by DAQO-702038-02. The permit was modified to allow the usage of a diesel generator on the power plant site. The Air Quality Permit covers both the power plant and mine site. The power plant site is not regulated by DOGM.

Permit Number: C0070035  
Inspection Type: COMPLETE  
Inspection Date: Tuesday, March 15, 2011

**21. Bonding and Insurance**

A Pledge and Escrow agreement dated January 4, 2002 is in place. The escrow agency is Wells Fargo for SCA. SCA has invested \$1,780,250.19 in federally guaranteed Treasury Notes as of December 31, 2006. The required bond amount is \$1,720,000.