GARY R. HERBERT
Governor
GREG BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 3, 2018
Start Date/Time:	4/3/2018 12:00:00 PM
End Date/Time:	4/3/2018 3:30:00 PM
Last Inspection:	Monday, March 19, 2018

Inspector: Steve Demczak,
Weather: Temp 40's, Cloudy, Dry Conditions
InspectionID Report Number: 6124
Accepted by: DHADDOCK
5/7/2018

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Steve Demczak

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
Site: **SUNNYSIDE REFUSE & SLURRY**
Address: **PO BOX 159, SUNNYSIDE UT 84539**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

241.25	**Total Permitted**
196.65	**Total Disturbed**
5.35	**Phase I**
5.35	**Phase II**
5.35	**Phase III**

Mineral Ownership

- ☐ **Federal**
- ☐ **State**
- ☐ **County**
- ☐ **Fee**
- ☐ **Other**

Types of Operations

- ☐ **Underground**
- ☐ **Surface**
- ☐ **Loadout**
- ☐ **Processing**
- ☑ **Reprocessing**

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee was in the process of mining some of the refuse piles from the Old Sunnyside Mine. This is within the disturbed area and approved in the MRP.

Stephen J. Demczak

Inspector's Signature:

Date Monday, April 23, 2018

Steve Demczak,
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

OIL, GAS & MINING

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☑	☐	☑	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☑	☐	☑	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☑	☐	☑	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☑	☐	☑	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☑	☐	☑	☐
16.b Roads: Drainage Controls	☑	☐	☑	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

1. Permits, Change, Transfer, Renewal, Sale

There are no permitting actions with the Division at this time.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm.

4.a Hydrologic Balance: Diversions

I inspected the diversions and culverts. The permittee cleaned out several diversions since the last inspection. These structures would function as designed. See Photo

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as designed. I did not see any hazardous conditions to these structures.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active. The permittee was mining some of the refuse for fuel for the power plant.

8. Noncoal Waste

The site was clean of non-coal waste materials such as trash, oil cans, and scrap materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as designed. See Photos