



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070035
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, May 8, 2019
Start Date/Time:	5/8/2019 12:00:00 PM
End Date/Time:	5/8/2019 4:00:00 PM
Last Inspection:	Thursday, April 4, 2019

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Steve Demczak

Inspector: Steve Demczak
 Weather: Cloudy, dry Conditions, 50's
 InspectionID Report Number: 6422
 Accepted by: SCHRISTE
 5/23/2019

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **SUNNYSIDE REFUSE & SLURRY**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
241.25	Total Permitted	<input type="checkbox"/> Federal	<input type="checkbox"/> Underground
196.65	Total Disturbed	<input type="checkbox"/> State	<input type="checkbox"/> Surface
5.35	Phase I	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
5.35	Phase II	<input type="checkbox"/> Fee	<input type="checkbox"/> Processing
5.35	Phase III	<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Sunnyside Co-Gen was in the process of reclaiming a spoil /refuse. It is the material that a Co-Gen plant cannot use. The reclamation equipment is on site. See Photos

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
 Inspector ID Number: 39

Date Monday, May 20, 2019



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

DOGMA Permit - The permit expires on Feb 4, 2023.

-UPDES permit #UT0024759 effective Feb. 28, 2019 and expires midnight Feb 29, 2024. Currently still under old permit until new permit is approved.

-SPCC plan is only applicable to plant site which is not within the permit area. (Feb. 9, 2016)

-Certificate of Insurance effective 2/3/2018 and terminates 2/3/2020.

-Reclamation agreement is dated December 1996 and signed by both parties.

- There are no permitting actions with the Division at this time.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as design during a storm event. The structures were recently re-graded and clean out of sediment. See photos

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as design. I did not see any hazardous conditions to these structures. The permittee conducted a first quarter sediment pond inspections on March 28, 2019. No hazardous conditions were reported.

4.d Hydrologic Balance: Water Monitoring

Water monitoring information is taken by the permittee and is sent electronically to the Division in Salt Lake City. This information is reviewed and analyzed by the Division staff. A report is written.

4.e Hydrologic Balance: Effluent Limitations

The permittee was in compliance with the UPDES permit for the first quarter of 2019. No discharge had occurred.

6. Disposal of Excess Spoil, Fills, Benches

The permittee will be reclaiming a spoil pile in the next couple of weeks pending weather conditions. The equipment is on site. See Photos

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active. The permittee conducted a first quarter refuse pile inspection on March 28, 2019. This document is P.E. certified. No hazardous conditions were reported. See Photos

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The mine site appears to be stable.

12. Backfilling And Grading

Backfilling and grading will occur on the reclaiming of the spoil pile in the next couple of weeks.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem. The roads were wet and had been recently water.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as design. See Photos

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

19. AVS check

AVS checks are made in Salt Lake City.

20. Air Quality Permit

Permit number is #70030004

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,775,000, as of December 31, 2006. Insurance is by Arch Insurance Company. The policy number is EPO101140501 and expires on February 3, 2020.

SUNNYSIDE **G**ENERATION

ASSOCIATES

(801)888-4476

P.O. BOX 10
EAST CARBON, UTAH 84520
PERMIT # ACT 007/035





