



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

| | |
|------------------|------------------------------|
| Permit Number: | C0070035 |
| Inspection Type: | PARTIAL |
| Inspection Date: | Thursday, September 19, 2019 |
| Start Date/Time: | 9/19/2019 12:00:00 PM |
| End Date/Time: | 9/19/2019 4:00:00 PM |
| Last Inspection: | Tuesday, August 20, 2019 |

| Representatives Present During the Inspection: | |
|--|---------------|
| Company | Rusty Netz |
| OGM | Steve Demczak |

Inspector: Steve Demczak

Weather: Sunny, 80's, Dry Conditions

InspectionID Report Number: 6530

Accepted by: SCHRISTE

9/30/2019

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**

Operator: **SUNNYSIDE COGENERATION ASSOCIATES**

Site: **SUNNYSIDE REFUSE & SLURRY**

Address: **PO BOX 159, SUNNYSIDE UT 84539**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

| | |
|--------|------------------------|
| 241.25 | Total Permitted |
| 196.65 | Total Disturbed |
| 5.35 | Phase I |
| 5.35 | Phase II |
| 5.35 | Phase III |

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The power plant was active receiving, burning coal and generating power.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Thursday, September 19, 2019



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS check | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

1. Permits, Change, Transfer, Renewal, Sale

There are no amendments under review with the Division.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm.

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as design during a storm event. The structures were recently re-graded and clean out of sediment. See photos

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as design. I did not see any hazardous conditions to these structures.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active. The permittee was mining some to the refuse for fuel for the power plant.

8. Noncoal Waste

The site was clean of non-coal waste materials such as trash, oil cans, wood and scrap materials.

10. Slides and Other Damage

No slides or other damage was notice during the inspection.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem. The roads were wet and had been recently water.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as design. See Photos

Permit Number: C0070035
Inspection Type: PARTIAL
Inspection Date: Thursday, September 19, 2019

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.



Service Guidelines
Access
Restrictions





