Hydrocarbon Issue

08311998

C007/0038



Return Portal Frac Tank

To Separate Mine Water

From Hydrocarbons

Water Clarity in Willow Creek Channel

Hydrocarbon Issue

08311998

C007/0038

Hydrocarbon Oil on Water Surface in Ditch Behind Warehouse/Shop







CYPRUS PLATEAU MINING CORPORATION
WILLOW CREEK MINE
MSHA I.D. NO. 42-02113
SCHOOL HOUSE CANYON
REFUSE PILE MSHA I.D. NO.
1211-UT-09-00165-01

Hydrocarbon Issue

08311998

C007/0038

Pond 001A Pump Used to Pump
Pond 001A Water From bottom
of Pond Into Neilsen Trucks.
Trucks Then Haul to Pond 013A

Willow Plantings in Willow Creek Channel

Pacific West Emergency

Response Team at Pond 001A

2" Primary Outlets Plugged on

Primary Spillway During

Hydrocarbon Issue

(Encountered 08/26/1998)