

Outgoing

0070038

OK

From: Steve Demczak
To: Angela Nance; Dennis Ware; Suzanne Steab
Date: 8/3/2010 7:08 AM
Subject: July Insp. Report
Attachments: 20100803072451.pdf; 20100803072507.pdf; 20100803072427.pdf



The State of Utah
 Department of
 Natural Resources

Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
 Executive Director

LOWELL P. BRAXTON
 Division Director

OLENE S. WALKER
 Governor

GAYLE F. McKEACHNIE
 Lieutenant Governor

Representatives Present During the Inspection:	
Company	Dennis Ware
OGM	Steve Demczak

Inspection Report

Permit Number:	C0070038
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, July 21, 2010
Start Date/Time:	7/21/2010 2:00:00 PM
End Date/Time:	7/21/2010 4:00:00 PM
Last Inspection:	Tuesday, June 22, 2010

Inspector: Steve Demczak

Weather: Sunny, 90's

InspectionID Report Number: 2435

Accepted by: jhelfric
 7/29/2010

Permitee: **PLATEAU MINING CORP**
 Operator: **PLATEAU MINING CORP**
 Site: **WILLOW CREEK MINE**
 Address: **PO BOX 30, HELPER UT 84526-0030**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

14,662.49	Total Permitted
71.44	Total Disturbed
125.41	Phase I
92.45	Phase II
92.45	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division that the fourth quarter of 2009 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading.
 The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2006.
 There are no pending compliance actions.
 There is currently no activity at this site.

Inspector's Signature: Date Monday, July 26, 2010
 Steve Demczak,
 Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Permit Number: C0070038
 Inspection Type: PARTIAL
 Inspection Date: Wednesday, July 21, 2010

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2. Signs and Markers

The identification signs is next to the road to the property. The information meets the R645 Coal Rules.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function during a storm event. No major storms have taken place since the last inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaimed area is pocked for sediment control.

7. Coal Mine Waste, Refuse Piles, Impoundments

The reclaimed refuse pile was inspected with no hazardous conditions noticed during the inspection.

8. Noncoal Waste

The site is clear of non-coal waste material.

10. Slides and Other Damage

The site is clear of non-coal waste material.

12. Backfilling And Grading

The total disturb area is reclaimed and is backfilled and graded.

13. Revegetation

The site has been seeded. Vegetation is growing on the site.

18. Support Facilities, Utility Installations

There are no facilities.