



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: Complete: Exploration: XXX
Inspection Date & Time: 10/29/96 / 10:00a.m.-11:00a.m.
Date of Last Inspection: 4/3/96

Mine Name: Dugout Exploration County: Carbon Permit Number: ACT/007/039
Permittee and/or Operator's Name: Soldier Creek Coal Company
Business Address: P.O. Box 1029, Wellington, Utah 84542
Type of Mining Activity: Underground Surface Prep. Plant Other XXX
Company Official(s): Keith Zobell
State Officials(s): Steve Demczak Federal Official(s): None
Weather Conditions: 5" Snow, 33°
Existing Acreage: Permitted- Disturbed- Regraded- Seeded- Bonded-
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: XXX Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows list 21 inspection items such as PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; etc.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/039

DATE OF INSPECTION: 10/29/96

(Comments are Numbered to Correspond with Topics Listed Above)

**1. PERMIT -**

The permittee has submitted, to the Division, a Mining and Reclamation Plan. It is anticipated that a permit maybe granted in the spring of 1997.

**3. TOPSOIL -**

The growth material was being protected by berms. This material was covered by snow.

**4C. OTHER SEDIMENT CONTROL MEASURES -**

The berms and silt fences appeared to be functioning as designed. The areas were covered with 5 inches of snow.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Keith Zobell (ARCO) Marcia Petta (OSM)  
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office  
Date: October 30, 1996

Inspector's Signature:  #39  
Stephen J. Demczak