

PRISCILLA,

Incoming  
C/007/0039  
Copy Priscilla

These are color copies of the soil  
AREAS FOR the DRILL SITE IN PACE  
CANYON. THE REPORT WITH  
BLACK & WHITE PHOTOS WAS SUBMITTED  
FOR REVIEW 5/26/04.

Vicky

RECEIVED  
MAY 27 2004  
OGM PRICE FIELD OFFICE

File in: C/0070039 Incoming  
Refer to Date Folder 05262004  
 Confidential  
 Shelf  
 Expandable  
For additional information



Photo No. 1 A view of drill site DUG0104 looking from across the stream.

RECEIVED

MAY 27 2004

OCM PRICE FIELD OFFICE



Photo No. 2 A view along the cut slope at drill site DUG0104. The most suitable topsoil is above the cut bank on the left side.



Photo No. 3 Suitable topsoil up to 18 inches thick was noted over a lighted colored more clayey subsoil.

RECEIVED

MAY 27 2004

OGM PRICE FIELD OFFICE



Photo No. 4 Bouldery spot in a slight drainage along the upper slope at drill site DUG0104. Looking up slope from the edge of the road.



Photo No. 5 A view of the fill slope at the edge of drill site DUG0104 near the stream.

RECEIVED

MAY 27 2004

OGM PRICE FIELD OFFICE



Photo No. 6 View of drill site DUG0204 looking down the road.



Photo No. 7 View of drill site DUG0204 looking up the road.

RECEIVED

MAY 27 2004

OGM INDIAN FIELD OFFICE