

OK



**State of Utah**  
**Department of**  
**Natural Resources**

MICHAEL R. STYLER  
*Executive Director*

**Division of**  
**Oil, Gas & Mining**

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

Representatives Present During the Inspection:	
OGM	Priscilla Burton Environmental Scientist III
Company	Vicky S. Miller Environmental Specialist

**Inspection Report**

Permit Number:	C0070039
Inspection Type:	TECHNICAL
Inspection Date:	Monday, November 24, 2008
Start Date/Time:	11/24/2008 1:00:00 PM
End Date/Time:	11/24/2008 4:30:00 PM
Last Inspection:	Thursday, October 23, 2008

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 50 F

InspectionID Report Number: 1848

Accepted by: jhelfric  
 12/8/2008

Permitee: **CANYON FUEL COMPANY LLC**  
 Operator: **CANYON FUEL COMPANY LLC**  
 Site: **DUGOUT CANYON MINE**  
 Address: **PO BOX 1029, WELLINGTON UT 84542**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

Current Acreages	
9,471.00	Total Permitted
51.10	Total Disturbed
	Phase I
	Phase II
	Phase III

- Mineral Ownership**
- Federal
  - State
  - County
  - Fee
  - Other

- Types of Operations**
- Underground
  - Surface
  - Loadout
  - Processing
  - Reprocessing

**Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:**

Observed ongoing topsoil salvage from G 22 access road and pad. Observed partially constructed topsoil stockpile on pad of G17. Photos from this site visit are located in the 11242008 images folder.

Inspector's Signature: *Priscilla Burton*

Priscilla Burton, Environmental Scientist III  
 Inspector ID Number: 37

Date Monday, December 01, 2008

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070039  
 Inspection Type: TECHNICAL  
 Inspection Date: Monday, November 24, 2008

Inspection Continuation Sheet

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

The G-22 pad and access road construction was approved on November 10, 2008. Two rock trucks, two dozers and a hoe were operating to salvage and stockpile topsoil from G-22 onto the location of the abandoned G-17 site.

**3. Topsoil**

Topsoil pile under construction was kidney bean shaped: approximately 30 ft long X 20 ft. wide X 12 ft high. Topsoil stockpile surrounds several quaken aspen trees. Photo attached. Additional topsoil will be stockpiled on an adjacent sagebrush flat, to the west on the existing road from G17.

**4.c Hydrologic Balance: Other Sediment Control Measures**

Silt fence was installed below constructed road. Photo attached

**18. Support Facilities, Utility Installations**

G-22 pad was under construction with cut slope approximately 7 ft. high. One-quarter to one-third of the site had been stripped of topsoil and leveled. Photo attached.