



The State of Utah

Department of  
Natural Resources

Division of  
Oil, Gas & Mining

ROBERT L. MORGAN  
*Executive Director*

LOWELL P. BRAXTON  
*Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

Representatives Present During the Inspection:	
Company	Vicky Miller
OGM	Steve Demczak

# Inspection Report

Permit Number:	C0070039
Inspection Type:	COMPLETE
Inspection Date:	Thursday, February 24, 2011
Start Date/Time:	2/24/2011 10:00:00 AM
End Date/Time:	2/24/2011 4:00:00 PM
Last Inspection:	Sunday, January 23, 2011

Inspector: Steve Demczak

Weather: Snow Covered, 20's

InspectionID Report Number: 2662

Accepted by: jhelfric  
3/3/2011

Permittee: **CANYON FUEL COMPANY**  
 Operator: **CANYON FUEL COMPANY**  
 Site: **DUGOUT CANYON MINE**  
 Address: **PO BOX 1029, WELLINGTON UT 84542**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

### Current Acreages

9,751.00	Total Permitted
108.70	Total Disturbed
	Phase I
	Phase II
	Phase III

### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.  
 The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2009.

Inspector's Signature:

Steve Demczak,

Inspector ID Number: 39

Date Monday, February 28, 2011

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

**Utah!**  
Where ideas connect™

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

DOGM Permit will expire on March 17, 2013. Air Quality permit number is DAQUE-AN0116340009-07. UPDES permit number is UT0025593 and expire on Nov. 30, 2014. The SPCC Plan was reviewed on March 14, 2008.

**2. Signs and Markers**

The permit sign is located at the gate to the property. Information meets the minimum requirements of the R645 Coal Rules.

**3. Topsoil**

There was no signs of wind or water erosion to the topsoil piles. Some of the topsoil piles are snow covered.

**4.a Hydrologic Balance: Diversions**

Diversions are snow covered. No water was melting during the inspection.

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The permittee inspected the mine sediment ponds on Oct. 6, 2010 and waste rock pond on Oct.6, 2010. The sediment pond is close to discharging. Depending of weather and other factors, this pond could discharge in the near future.

**4.d Hydrologic Balance: Water Monitoring**

Water Monitoring for third quarter has been submitted to the Division for review. This information will be reviewed by the Staff in Salt Lake.

**4.e Hydrologic Balance: Effluent Limitations**

The Permittee has exceeded TDS in November and December on some water samples. Iron was exceeded in October and December of some water samples.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile was inspected on Oct. 14, 2010 with no hazardous conditions reported. I inspected the refuse piles and did not see any hazardous conditions.

**8. Noncoal Waste**

The mine site was clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides or other damage was noticed during the inspection.

**14. Subsidence Control**

Subsidence information was in the annual report.

Permit Number: C0070039  
Inspection Type: COMPLETE  
Inspection Date: Thursday, February 24, 2011

**18. Support Facilities, Utility Installations**

No new support facilities were constructed since the last inspection.

**21. Bonding and Insurance**

The insurance policy will expire on July 31, 2011. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 104.70 acres.