



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070039
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 07, 2012
Start Date/Time:	8/7/2012 9:00:00 AM
End Date/Time:	8/7/2012 4:00:00 PM
Last Inspection:	Wednesday, July 18, 2012

Representatives Present During the Inspection:	
Company	Vicky Miller
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 3213

Accepted by: jhelfric  
9/6/2012

Permitee: **CANYON FUEL COMPANY**  
 Operator: **CANYON FUEL COMPANY**  
 Site: **DUGOUT CANYON MINE**  
 Address: **PO BOX 1029, WELLINGTON UT 84542**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

#### Current Acreages

9,801.00	<b>Total Permitted</b>
108.70	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing


#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.

Inspector's Signature:

Steve Demczak,  
Inspector ID Number: 39

Date Wednesday, August 07, 2012



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

DOGMA Permit will expire on March 17, 2013. Air Quality permit number is DAQUE-AN0116340009-07. UPDES permit number is UT0025593 and expire on Nov. 30, 2014. The SPCC Plan was reviewed on October 25, 2010.

**2. Signs and Markers**

The permit sign is located at the gate to the property. Information meets the minimum requirements of the R645 Coal Rules.

**3. Topsoil**

There was no signs of wind or water erosion to the topsoil piles.

**4.a Hydrologic Balance: Diversions**

Diversions were functioning as designed. Culverts were opened.

**4.e Hydrologic Balance: Effluent Limitations**

Second quarter UPDES samples were in compliance with their UPDES requirements.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile was inspected on May 24, 2012. No hazardous conditions were reported. I inspected the pile and did not see any hazardous conditions.

**8. Noncoal Waste**

The mine site was clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides or other damage was noticed during the inspection.

**14. Subsidence Control**

Subsidence information for 2011 will be submitted in the 2012 annual report.

**16.b Roads: Drainage Controls**

Road drainage was function as designed.

**18. Support Facilities, Utility Installations**

No new construction has occurred since the last inspection.

**19. AVS Check**

AVS checks are made at the Division in SLC.

Permit Number: C0070039  
Inspection Type: COMPLETE  
Inspection Date: Tuesday, August 07, 2012

**20. Air Quality Permit**

Permit is DAQE-AN116340009-07

**21. Bonding and Insurance**

The insurance policy will expire on July 31, 2013. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 104.70 acres.