



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070039
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 06, 2013
Start Date/Time:	8/6/2013 10:00:00 AM
End Date/Time:	8/6/2013 3:00:00 PM
Last Inspection:	Wednesday, July 10, 2013

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 3572

Accepted by: jhelfric

8/26/2013

Representatives Present During the Inspection:	
OGM	Daron Haddock
Company	David Spillman
OGM	Steve Demczak

Permitee: **CANYON FUEL COMPANY**
 Operator: **CANYON FUEL COMPANY**
 Site: **DUGOUT CANYON MINE**
 Address: **PO BOX 1029, WELLINGTON UT 84542**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

9,801.00	Total Permitted
108.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Dugout mine is producing coal with one miner section , two shifts per day, five days per week.

Dugout has plans to reclaim several de-gas pads and roads this year.

Dugout will be today will be shutting down the mine fan at Pace Canyon today. The mine does not need extra air for ventilation since they are not longwall mining.

Steve Demczak

Digitally signed by Steve Demczak
 DN: cn=Steve Demczak, o, ou,
 email=stevedemczak@utah.gov, c=US
 Date: 2013.10.07 14:58:12 -06'00'

Inspector's Signature:

Steve Demczak,
 Inspector ID Number: 39

Date Thursday, August 08, 2013



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit expires on March 16, 2018. Air Quality permit number is DAQUE-AN0116340009-07. UPDES permit number is UT0025593 and expire on Nov. 30, 2014. The SPCC Plan was reviewed on October 25, 2010.

2. Signs and Markers

I reviewed the identification signs at the mine, the information on the sign meeting the minimum requirements of the R645 Coal Rules. It is next to the gate entering the mine site. There are also identification signs at the refuse pile and topsoil pile. The information is the same on all signs.

3. Topsoil

I inspected the topsoil piles and they were stable with no signs of erosion. There is some vegetation growth on the piles.

4.a Hydrologic Balance: Diversions

The diversions were clear from obstruction and the culverts were open. They have been functioning as design in the recent rainstorms.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected by the permittee for the second quarter on May 23, 2013. No hazardous conditions were reported. The slope of the sediment ponds appear to be stable with no signs of erosion. The mine site sediment pond contained water but was not discharging. The refuse pile sediment pond was dry.

4.d Hydrologic Balance: Water Monitoring

The water monitoring information is examined in Salt Lake City.

4.e Hydrologic Balance: Effluent Limitations

There was no discharge from the UPDES points for the second quarter of 2013.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected by the permittee on May 23, 2013. This document is P.E. certified. No hazardous conditions were reported. I inspected the refuse pile and the permittee was using the pill during the inspection. The pile appears to be stable with no signs of any hazardous conditions.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

16.a Roads: Construction, Maintenance, Surfacing

The permittee patch the road to the office.

16.b Roads: Drainage Controls

Road drainage was functioning as design.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2013. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturbed area is 104.70 acres.