

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Page 1 of 2	
Permit Number	ACT/007/039	Report Date	9/25/2017
Mine Name	Dugout Canyon Mine		
Company Name	Canyon Fuel Company, LLC		
Impoundment Identification	Impoundment Name	Refuse Pile Sedimentation Pond	
	Impoundment Number	None	
	UPDES Permit Number	UT0025593	
	MSHA ID Number	Impoundment -None (Refuse Pile 1211-UT-09-01890-01)	
IMPOUNDMENT INSPECTION			
Inspection Date	9/13/2017		
Inspected By	Bill King		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Quarterly Inspection		
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p><i>Construction of the Refuse Pile Sedimentation Pond has been completed in accordance with the approved plan. There were no signs instability, structural weakness or other hazardous conditions observed during this inspection.</i></p>			
Required for an impoundment which functions as a SEDIMENTATION POND.	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p><i>Sediment Storage Capacity (as-built) - 100% = 0.67 acre-feet @ an elevation of 5,897.55 feet</i> <i>- 60% = 0.40 acre-feet @ an elevation of 5,896.5 feet</i> <i>At the time of the inspection, the estimated average elevation of the existing sediment was 5,895.5 feet.</i></p>		
	<p>3. Principle and emergency spillway elevations.</p> <p><i>Emergency Spillway Elevation (as-built) - 5,902.5 feet</i></p>		
<p>4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on out slopes of embankments, etc.</p> <p><i>The pond was dry at the time of the inspection.</i></p> <p><i>Sediment levels were observed as being below the established 60% levels.</i></p> <p><i>This pond has never discharged.</i></p>			

