

0015

*Outgoing*

*0070042*

*Q*

**From:** Karl Houskeeper  
**To:** rnetz@emerytelcom.net  
**CC:** Angela Nance; Daron Haddock; Suzanne Steab  
**Date:** 9/15/2009 10:24 AM  
**Subject:** August 2009 Inspection Reports  
**Attachments:** SCA August 2009.pdf; SPWF August 2009.pdf

Rusty,

Attached are the August 2009 inspection reports for SPWF nad SCA.

Thanks,  
Karl



**State of Utah**  
**Department of**  
**Natural Resources**

MICHAEL R. STYLER  
*Executive Director*

**Division of**  
**Oil, Gas & Mining**

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

Representatives Present During the Inspection:	
OSM	Christine Belka Environmental Protection Specialist
OGM	Karl Houskeeper Environmental Scientist III
Company	Richard Safley

# Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE OVERSITE
Inspection Date:	Wednesday, August 26, 2009
Start Date/Time:	8/26/2009 8:30:00 AM
End Date/Time:	8/26/2009 11:30:00 AM
Last Inspection:	Thursday, July 16, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 88 Deg. F.

InspectionID Report Number: 2110

Accepted by: jhelfric

9/14/2009

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**

Operator: **SUNNYSIDE COGENERATION ASSOCIATES**

Site: **STAR POINT REFUSE**

Address: **ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

**Current Acreages**

152.93	<b>Total Permitted</b>
152.93	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

**Mineral Ownership**

- Federal
- State
- County
- Fee
- Other

**Types of Operations**

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: \_\_\_\_\_

*Karl Houskeeper*

Date Wednesday, August 26, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • [www.ogm.utah.gov](http://www.ogm.utah.gov)

Permit Number: C0070042  
 Inspection Type: COMPLETE OVERSITE  
 Inspection Date: Wednesday, August 26, 2009

Inspection Continuation Sheet

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## **1. Permits, Change, Transfer, Renewal, Sale**

The following permits were reviewed:

- Mining permit C/007/042 issued November 14, 2008 and expires November 14, 2013.
- UPDES permit #UTG040025 effective May 1, 2008 and expires midnight April 30, 2013 (under general permit UTG040000).
- Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.
- SPCC plan is not required.
- Certificate of Insurance effective 08/01/2009 and terminates 08/01/2010.
- Reclamation agreement is dated October 14, 2003 and signed by both parties.
- Storm Water Permit UTR000604, effective 01/01/07 and expires @ midnight 12/31/11 (under general permit UTR000000).

## **2. Signs and Markers**

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

## **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Second quarter 2009 sediment pond inspections were done on June 25, 2009 and included in a report dated July 20, 2009. The reports were P.E. certified.

## **4.c Hydrologic Balance: Other Sediment Control Measures**

The pre-sediment treatment basins have been cleaned. Recent storm events have filled the pre-treatment basins with water.

## **4.e Hydrologic Balance: Effluent Limitations**

Reviewed the June 2009 discharge monitoring reports. No discharges occurred.

## **7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile was inspected in the second quarter of 2009 on June 25, 2009. The report is dated July 20, 2009.

## **20. Air Quality Permit**

The air quality permit DAQE-239-02 was issued on April 1, 2002 and remains in effect.

## **21. Bonding and Insurance**

The bond is a collateral bond in the amount of \$1,375,737.31, as of December 31, 2006.