

Outgoing
0070042
R

Suzanne Steab - May 2011 Inspection Reports

From: Karl Houskeeper
To: rnetz@emerytelcom.net
Date: 6/1/2011 3:49 PM
Subject: May 2011 Inspection Reports
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: SCA May 2011.pdf; SPWF May 2011.pdf

Rusty,

Attached are the May 2011 inspection reports for SCA and SPWF.

Thanks,
Karl



State of Utah
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, May 10, 2011
Start Date/Time:	5/10/2011 12:00:00 PM
End Date/Time:	5/10/2011 3:00:00 PM
Last Inspection:	Tuesday, April 05, 2011

Representatives Present During the Inspection	
Company	Rusty Netz
OGM	Karl Houskeeper
OGM	Priscilla Burton

Inspector: Karl Houskeeper

Weather: Overcast/Snowing, Temp. 31 Deg.F.

Inspection ID Report Number: 2738

Accepted by: jhelfric
 5/12/2011

Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **STAR POINT REFUSE**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

152.93	Total Permitted
152.93	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Area is blanketed by a snow storm that occurred today. Approximately 2 - 4 inches of snow is covering the entire site. Workers were shutting down the operation to the wet conditions. Priscilla Burton (UDOGM) joined Rusty Netz (Permittee) and I for the latter part of the inspection.

Inspector's Signature: _____

Karl Houskeeper

Date

Tuesday, May 10, 2011



Karl Houskeeper,

Inspector ID Number: 49

Note: This inspection report was conducted in accordance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070042
 Inspection Type: COMPLETE
 Inspection Date: Tuesday, May 10, 2011

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The following permits were reviewed:

- Mining permit C/007/042 issued November 14, 2008 and expires November 14, 2013.
- UPDES permit #UTG040025 effective May 1, 2008 and expires midnight April 30, 2013 (under general permit UTG040000).
- Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.
- SPCC plan is not required.
- Certificate of Insurance effective 08/01/2010 and terminates 08/01/2011.
- Reclamation agreement is dated October 14, 2003 and signed by both parties.
- Storm Water Permit UTR000604, effective 01/01/07 and expires @ midnight 12/31/11 (under general permit UTR000000).

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

First quarter 2011 sediment pond inspections were done on March 24, 2011 and P.E. certified on April 25, 2011.

4.e Hydrologic Balance: Effluent Limitations

The January, February, March and April 2011 discharge monitoring reports were reviewed during the inspection. No discharges occurred from any of the outfalls during the referenced months.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected in the First quarter of 2011 on March 24, 2010 and P.E. certified on April 25, 2011. The pile appeared stable. No visible hazards were observed. A comparison of the 2009 and 2010 Annual Report Mine Maps shows a lowering of the pile surface by twenty feet in the last year, to an elevation of 7130 ft. on the west end and 7480 ft. on the east end.

20. Air Quality Permit

The air quality permit DAQE-239-02 was issued on April 1, 2002 and remains in effect.

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,375,737.31, as of December 31, 2006.