

Outgoing
0070042

K

Suzanne Steab - August 2011 Inspection Report

From: Karl Houskeeper
To: rnetz@emerytelcom.net
Date: 9/15/2011 1:58 PM
Subject: August 2011 Inspection Report
CC: ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov
Attachments: SCA August 2011.pdf; SPWF August 2011.pdf

Rusty,

Attached are the August 2011 inspection reports for SCA and SPWF.

Thanks,
Karl



State of Utah
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, August 17, 2011
Start Date/Time:	8/17/2011 11:30:00 AM
End Date/Time:	8/17/2011 2:00:00 PM
Last Inspection:	Wednesday, July 06, 2011

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Clear, Temp. 78 Deg. F.

InspectionID Report Number: 2834

Accepted by: jheltric
 8/18/2011

Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **STAR POINT REFUSE**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
152.93	Total Permitted	<input type="checkbox"/> Federal	<input type="checkbox"/> Underground
152.93	Total Disturbed	<input type="checkbox"/> State	<input type="checkbox"/> Surface
	Phase I	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
	Phase II	<input checked="" type="checkbox"/> Fee	<input type="checkbox"/> Processing
	Phase III	<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: _____

Karl Houskeeper

Date Wednesday, August 17, 2011

Karl Houskeeper,
 Inspector ID Number: 49

Note: This inspection report does not constitute an offer of insurance or any other financial product. It is a report of the Division of Oil, Gas and Mining, telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070042
 Inspection Type: PARTIAL
 Inspection Date: Wednesday, August 17, 2011

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070042
Inspection Type: PARTIAL
Inspection Date: Wednesday, August 17, 2011

Inspection Continuation Sheet

Page 3 of 3

2. Signs and Markers

The mine identification sign is located along side of the county road as you enter the permit area. The sign is in good repair and contains of the required information.

4.a Hydrologic Balance: Diversions

The culverts located on the inlet and outlet of the pre sediment basin have been excavated and replaced with earthen material instead of refuse . The soil was compacted in lifts. This repair work was done because erosion had channeled to the sides of the culverts.

The diversion culvert located on the top of the refuse pile that drains the entire surface has been lowered so that a new excavation lift can begin.

4.c Hydrologic Balance: Other Sediment Control Measures

The ore sediment basins have been cleaned out.

7. Coal Mine Waste, Refuse Piles, Impoundments

The surface of the refuse pile is being mined in lifts.

22. Other

Many of the thistle plants on the permit area have been removed. One area at the entrance to the surface of the refuse pile remains.