



State of Utah
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

| | |
|------------------|--------------------------|
| Permit Number: | C0070042 |
| Inspection Type: | PARTIAL |
| Inspection Date: | Wednesday, May 23, 2012 |
| Start Date/Time: | 5/23/2012 10:30:00 AM |
| End Date/Time: | 5/23/2012 12:30:00 PM |
| Last Inspection: | Thursday, April 12, 2012 |

| Representatives Present During the Inspection: | |
|--|-----------------|
| Company | Rusty Netz |
| OGM | Karl Houskeeper |

Inspector: Karl Houskeeper,

Weather: Clear, Temp. 67 Deg. F.

InspectionID Report Number: 3109

Accepted by: jhelfric
5/31/2012

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **STAR POINT REFUSE**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

| | |
|--------|------------------------|
| 152.93 | Total Permitted |
| 152.93 | Total Disturbed |
| | Phase I |
| | Phase II |
| | Phase III |

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Date: Wednesday, May 23, 2012

Karl Houskeeper,
Inspector ID Number: 49

Note: This inspection report is not a substitute for an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070042
 Inspection Type: PARTIAL
 Inspection Date: Wednesday, May 23, 2012

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

2. Signs and Markers

The mine identification sign is located on the left side of the county road used to access the permit area. The sign contains all the required information

4.c Hydrologic Balance: Other Sediment Control Measures

The sediment trap basin located adjacent to the county road is full and will need to be cleaned this summer. The sediment basin on the reverse side of the pile and by the mine identification sign are both still ok. They have some sediment in them, but still have remaining capacity.

7. Coal Mine Waste, Refuse Piles, Impoundments

The pile is still being actively mined. The surface of the refuse pile has decrease in elevation substantially since the inception of re-mining. The pile appears stable. No visible hazards were observed during the inspection.

8. Noncoal Waste

No noncoal waste items were observed within the permit area.