GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Representatives Present During the Inspection:	
Company	Richard Carter
OGM	Karl Houskeeper
OGM	Daron Haddock

Permit Number:	**C0070042**
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, August 14, 2013
Start Date/Time:	8/14/2013 11:00:00 AM
End Date/Time:	8/14/2013 1:00:00 PM
Last Inspection:	Thursday, July 18, 2013

Inspector: Karl Houskeeper,

Weather: Cloudy, Temp. 78 Deg. F.

InspectionID Report Number: 3580

Accepted by: jhelfric
8/26/2013

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
Site: **STAR POINT REFUSE**
Address: **PO BOX 159, SUNNYSIDE UT 84539**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

152.93	**Total Permitted**
152.93	**Total Disturbed**
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
- ☐ State
- ☐ County
- ☑ Fee
- ☐ Other

Types of Operations

- ☐ Underground
- ☐ Surface
- ☐ Loadout
- ☐ Processing
- ☑ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

A Dozer has been implemented to aid in the excavation of refuse material.

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Wednesday, August 14, 2013

Note: This inspection report does not constitute an official finding of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

Permit Number: C0070042
Inspection Type: PARTIAL
Inspection Date: Wednesday, August 14, 2013

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☑	☑	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The mine identification was observed on the left side of the carbon county road used to access the mining permit area. The sign contains the required information.

4.a Hydrologic Balance: Diversions

A segment of the culvert used to divert runoff from the surface of the refuse pile has been removed. A new lift of mining is being started from this point and will extended East and West.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards were observed during the partial inspection. A new lift of mining is beginning from the diversion and extending to the east and west of the refuse pile.

8. Noncoal Waste

The mining site was free of noncoal waste items.