

Print Form

Submit by Email

Reset Form

C/007/0042
Received 3/17/15
Task ID #4854

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Sunnyside Cogeneration Assoc.	Mine Name	Star Point Waste Fuel Refuse
Permit Number	C/007/0042	Permit expiration Date	2018-11-14
Operator Name	Plant Manager - Gerald Hascall	Phone Number	+1 (435) 888-4476
Mailing Address	PO Box 159	Email	
City	Sunnyside		
State	UT	Zip Code	84539

DOGGM File Location or Annual Report Location

Excess Spoil Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Refuse Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Other:		

OPERATOR COMMENTS

Sediment ponds, Refuse Pile and Excess Spoil Pile were inspected quarterly and PE Certified reports submitted to the division. All impoundments performed as designed. Only one discharge occurred during 2014 and it was well within the UPDES limits. The refuse pile is being excavated as intended and in conformance with the approved design. The Disposal Area / Excess Spoil Pile is in conformance with the approved plan. Two notices of violation were received during 2014. These were in relation to storm water ditches/culverts. Required site corrections were made promptly and the violations were abated.

REVIEWER COMMENTS

Met Requirements Did Not meet Requirements

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

SCA Excavated approximately 369.657 tons of refuse material from this site and transported it to the SCA Sunnyside Facility
No material was placed in the Disposal Area during 2014
Two permit amendments were processed and approved during 2014. Both were related to storm water controls (ditches/culverts)

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
Mine Map	1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Current mining plan is in the permit	#521.100 d and e	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements




**SCA-STARPOINT WASTE FUEL
REFUSE PILE MINE MAP**
Carbon County, Utah



DWG DATE: March 2015
PLOT DATE: 25 March 2015

SHEET
1
OF
1



- NOTES:
- CONTOURS SHOWN HERE ARE A COMBINATION OF:
 - 2' CONTOUR INTERVALS ARE BASED ON FLIGHT OF 4 / 2013
 - OTHER CONTOUR INTERVALS IN THE SURROUNDING AREAS ARE BASED ON RECORD INFORMATION OR PROVIDED BY SCA IN PREVIOUS YEARS
 - TICK MARKS PROVIDE A CUT DEPTH COMPARING 4 / 2013 ELEVATIONS WITH 5 / 2010 ELEVATIONS
 - 2014 MINING EXCAVATION OCCURRED WITHIN THE AREA OUTLINED IN RED
 - INSET PHOTO DOCUMENTS SITE CONDITIONS ON AUGUST 15, 2014