



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, November 18, 2015
Start Date/Time:	11/18/2015 9:00:00 AM
End Date/Time:	11/18/2015 12:00:00 PM
Last Inspection:	Monday, October 26, 2015

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: 30's, Sunny, Slightly Snow Covered

InspectionID Report Number: 5367

Accepted by: JHELFRIC
11/30/2015

Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **STAR POINT REFUSE**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

152.93	Total Permitted
152.93	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee was in the process of building small refuse piles on top of the main refuse pile. This is to have easier accesses for material during the winter months

Trucks were loading refuse during the inspection. This material was going to the Co-Gen plant.

There are no permitting actions on file at this time with the Division.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Thursday, November 19, 2015



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

DOGM Mining permit C/007/042 issued November 14, 2013 and expires November 14, 2018.

-UPDES permit #UTG040025 effective September 1, 2013 and expires @ midnight August 31, 2018.

-Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.

-Reclamation agreement is dated October 14, 2003 and signed by both parties.

There are no amendments with the Division for review at this time.

2. Signs and Markers

The identification signs were inspected and contain the required information as required in the R645 Coal Rules.

3. Topsoil

Topsoil piles are snow covered.

4.a Hydrologic Balance: Diversions

The diversions and culverts were open and would function during a rainstorm. See picture

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected with no hazardous conditions were noticed. The embankments, inlets and outlets were stable. The permittee conducted a quarterly inspection on September 24, 2015. In the report no constructional problems were noted. The sediment ponds did not discharge for the third quarter of 2015. There are three sediment ponds. They are #005, #006, and #009.

4.d Hydrologic Balance: Water Monitoring

The water monitoring information is submitted to the Division as required in the Mining and Reclamation Plan. This information is review and documented by Division staff in Salt Lake City.

4.e Hydrologic Balance: Effluent Limitations

No discharges for the third quarter.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile with no hazardous condition noticed. The embankments appeared to be stable. The permittee conducted a third quarter refuse pile inspection on September 24, 2015. The inspection report revealed no hazardous conditions.

8. Noncoal Waste

The site was clear of trash and other non-coal waste materials.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

16.b Roads: Drainage Controls

The road drainage controls were functioning as designed. Diversions and culverts were open. No water was flowing within the diversions during the inspection.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.

19. AVS Check

AVS checks are made in Salt Lake City.

20. Air Quality Permit

Air quality permit number is #7000300003

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,375,737.31, as of December 31, 2006. Insurance is by Author J. Gallagher Risk Management Services, Inc. The policy number is #35816976 and expires on August 1, 2016.

Star Point Waste Fuel
MSHA-ID #42-02334
SUNNYSIDE COGEN ASS.
C-007-042
REFUSE PILE.
1211-UT-09-02334-01

© 2009 Sunnyside Cogeneration, LLC 803.338.4400















