



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 30, 2016
Start Date/Time:	8/30/2016 9:00:00 AM
End Date/Time:	8/30/2016 12:00:00 PM
Last Inspection:	Tuesday, July 26, 2016

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 80's, Dry Ground Conditions

InspectionID Report Number: 5622

Accepted by: DHADDOCK
9/9/2016

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
 Site: **STAR POINT REFUSE**
 Address: **PO BOX 159, SUNNYSIDE UT 84539**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

152.93	Total Permitted
152.93	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Starpoint refuse pile was active during the inspection. A dozer was in the process of making wind rows for the drying and loading of refuse material. No trucks were getting loaded during the inspection.

The Starpoint site has not yet received a major August storm so far this year.

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Wednesday, August 31, 2016



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

DOGM Mining permit C/007/042 issued November 14, 2013 and expires November 14, 2018.

-UPDES permit #UTG040025 effective September 1, 2013 and expires @ midnight August 31, 2018.

-Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.

-Reclamation agreement is dated October 14, 2003 and signed by both parties.

There are no amendments with the Division for review at this time.

2. Signs and Markers

The identification sign located at the main gate to the refuse pile was inspected. The sign meets the minimum requirements of the R645 Coal Rules. See Picture

4.a Hydrologic Balance: Diversions

I inspected several diversions throughout the property. The diversion which was reconstructed this spring was inspected and is performing as design. See Picture
Culverts were open throughout the property.

I did not see any obstruction to these structures.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The permittee conducted a second quarter sediment pond inspection on June 30, 2016. No hazardous conditions were reported. This document is P.E. certified. I inspected the sediment ponds and did not see any hazardous conditions.

Embankments appear to be stable. No major erosion notice to the out slopes or in slopes. No sediment pond was discharging during the inspection. Sediment ponds were dry or nearly dry. See Pictures

4.d Hydrologic Balance: Water Monitoring

Water monitoring information is sent to the Division in Salt Lake City. This information is reviewed and a report is written.

4.e Hydrologic Balance: Effluent Limitations

There was no discharge from the sediment ponds for the second quarter of 2016. It is unlikely a discharge will occur for the third quarter of 2016.

7. Coal Mine Waste, Refuse Piles, Impoundments

The permittee conducted a second quarter refuse pile inspection on June 30, 2016. No hazardous conditions were reported. This document is P.E. Certified. I inspected the refuse pile and did not see any hazardous conditions. Embankments appear to be stable.

8. Noncoal Waste

The site was clear of non-coal waste material such as oil cans and trash.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

16.a Roads: Construction, Maintenance, Surfacing

Road diversions and culverts were open and the road has water added for dust control.

19. AVS Check

AVS Checks are made at the Division in Salt Lake City.

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,375,737.31, as of December 31, 2006. Insurance is by Author J. Gallagher Risk Management Services, Inc. The policy number is #35816976 and expires on December 31, 2016.