



Suzanne Steab <suzannesteab@utah.gov>

2017 Annual Report Review Completion

Suzanne Steab <suzannesteab@utah.gov>

Tue, Jun 12, 2018 at 9:48 AM

To: Rusty <rnetz@sscogen.com>

The Division staff completed the review of the 2017 Annual Report for the Star Point Refuse. Attached is a copy of the review with comments.

No hard copy will follow.

Thank you for your diligence in completing the Annual Report.

--

Suzanne Steab, Engineering Technician II
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801
(801) 538-5265



Star Point Refuse.pdf

35K

ANNUAL REPORT

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Sunnyside Cogeneration Assoc.	Mine Name	Star Point Waste Fuel
Permit Number	C/007/0042	Permit expiration Date	2018-11-14
Operator Name	Gerald Hascall, Plant Manager	Phone Number	+1 (435) 888-4476
Mailing Address	PO Box 159	Email	
City	Sunnyside		
State	Utah	Zip Code	84539

DOG M File Location or Annual Report Location

Excess Spoil Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Refuse Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Other:		

OPERATOR COMMENTS

Sediment Ponds, Refuse Pile and Excess Spoil Disposal Area were inspected quarterly and PE Certified reports were submitted to the Division.

All impoundments performed as designed. No discharges were recorded in 2017.

Refuse Pile is being excavated as intended and in conformance with the approved plan.

One permit amendment was completed in 2017 to update corporate ownership.

REVIEWER COMMENTS

Met Requirements Did Not Meet Requirements

Incoming quarterly inspection reports have been submitted to the Division for all of the sediment ponds and refuse piles on site. Quarterly inspections were conducted on the following dates: 3/23/2017, 6/29/2017, 9/28/2017, and 12/28/2017. The approximate volume of material removed from the coarse refuse pile was 235,250 tons in 2017. The active bench elevation is reported to be 7,450 -7,480 ft. The results of the quarterly inspections during 2017 revealed that all of the impoundments appeared stable, and showed no signs of instability, structural weakness, or any other hazardous conditions. The coarse refuse pile displayed some old erosional gullies on the outer slopes, but overall appeared stable. All reports were signed and stamped by S. Scott Carlson, a licensed professional engineer in the State of Utah. JE

FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.



Title: SOIL SAMPLING

Objective: To ensure four feet of suitable material.

Frequency: At final reclamation sample for parameters described in Section 242 and Sec. 542.700

Status: During reclamation

Reports: Confer with Division and include in Annual Report

Citation: Vol 1 Sec. 242

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

In 2017, SCA excavated approximately 238,508 tons of refuse material from this site and transported it to the SCA Sunnyside facility. No new material was placed in the disposal area during 2017.

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
Mine Map	1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements