



Suzanne Steab <suzannesteab@utah.gov>

2018 Annual Report Review Completion

Suzanne Steab <suzannesteab@utah.gov>

Fri, May 31, 2019 at 8:29 AM

To: Rusty <rnetz@sscogen.com>

Cc: Keenan Storrar <kstorrar@utah.gov>, "Christensen, Steve" <stevechristensen@utah.gov>

The Division staff have completed the review of the 2018 Annual Report for the Star Point Refuse. Attached is a copy of the review with comments.

No hard copy will follow.

Thank you for your diligence in completing the Annual Report.

--

Suzanne Steab, Engineering Technician II
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801
(801) 538-5265

 **Star Point Refuse.pdf**
31K

2018 ANNUAL REPORT

Submit the completed document and any additional information identified to the Division by March 31, 2019.

GENERAL INFORMATION

Company Name	Sunnyside Cogeneration Assoc.	Mine Name	Star Point Waste Fuel
Permit Number	C/007/0042	Permit Expiration Date	2023-11-14
Operator Name	Gerald Hascall - Plant Manager	Phone Number	+1 (435) 888-4476
Mailing Address	PO Box 159	Email	
City	Sunnyside		
State	UT	Zip Code	84539

DOGM File Location or Annual Report Location

Excess Spoil Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Refuse Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted Quarterly to DOGM
Other:		

OPERATOR COMMENTS

Sediment Ponds, Refuse Pile and Excess spoil Disposal Area were inspected quarterly and PE Certified reports were submitted to the Division.

All impoundments performed as designed. No discharges were recorded in 2018

Refuse Pile is being excavated as intended and in conformance with the approved plan

Permit renewal was completed in 2018

REVIEWER COMMENTS

Met Requirements Did Not Meet Requirements

Incoming quarterly inspection reports have been submitted to the Division for all of the sediment ponds and refuse piles on site. Quarterly inspections were conducted on the following dates: 3/29/2018, 6/28/2018, 9/27/2018, and 12/27/2018. The active bench elevation is reported to be 7,430 -7,470 ft. The results of the quarterly inspections during 2017 revealed that all of the impoundments appeared stable, and showed no signs of instability, structural weakness, or any other hazardous conditions. The coarse refuse pile displayed some old erosional gullies on the outer slopes, but overall appeared stable. All reports were signed and stamped by S. Scott Carlson, a licensed professional engineer in the State of Utah. JE

FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

Title: SOIL SAMPLING

Objective: To ensure four feet of suitable material.

Frequency: At final reclamation sample for parameters described in Section 242 and Sec. 542.700

Status: During reclamation

Reports: Confer with Division and include in Annual Report

Citation: Section 242

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

In 2018, SCA excavated approximately 222,543 tons of refuse material from this site and transported it to the SCA Sunnyside facility. No new material was placed in the disposal area during 2018

REVIEWER COMMENTS

Met Requirements

Did Not Meet Requirements

