

9-22-88

2806

0007



3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 88-30-1-2

notice of violation

To the following Permittee or Operator:

Name WESTERN STATES MINERALS CORP.

Mine J.B. KINGS  Surface  Underground  Other

County EMERY State UT Telephone \_\_\_\_\_

Mailing Address 4975 VAN GORDON SB. WHEAT RIDGE, CO 80033

State Permit No. INA/015/002 7100

Ownership Category  State  Federal  Fee  Mixed

Date of inspection SEPTEMBER 7, 1988, 19\_\_\_\_.

Time of inspection 10:00  a.m.  p.m. to 11:30  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing SEPTEMBER 9, 1988 Time of service/ mailing 1:00  a.m.  p.m.

LARRY JOHNSON  
Permittee/Operator representative  
(MAILED FROM PRICE)  
Signature

\_\_\_\_\_  
Title  
RECLAMATION SPECIALIST  
\_\_\_\_\_  
Title  
#30  
\_\_\_\_\_  
Identification Number

BILL WARMACK  
Division of Oil, Gas & Mining representative  
William A. Warmack  
Signature

SEE REVERSE SIDE

WHITE-DOGMI YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

3001

9-22-88



NOTICE OF VIOLATION NO. NBB-30-1-2

Violation No. 1 of 2

Nature of violation

FAILURE TO MINIMIZE EROSION TO  
THE EXTENT POSSIBLE.

Provisions of act, regulations or permit violated

UMC 817.45  
UMC 817.106

Portion of operation to which notice applies

① EASTERN BACKFILL SLOPE SPECIFICALLY IN  
THE AREA WHERE SILT FENCES HAVE BEEN  
PREVIOUSLY INSTALLED; ② MAIN CHANNEL  
DIVERSION FROM HIGHWALL TO SEDIMENT  
POND.

Remedial action required (including any interim steps)

INSTALL OR CONSTRUCT NECESSARY EROSION  
CONTROL DEVICES, I.E., BEAMS, RIP-RAP,  
ETC.

Abatement time (including interim steps)

COMPLETE THE NECESSARY REPAIR WORK  
BY OCTOBER 28, 1988.

9-22-88



NOTICE OF VIOLATION NO. N 88-30-1-2

Violation No. 2 of 2

Nature of violation

FAILURE TO RESTORE SUBSIDENCE EFFECTED  
SURFACE LANDS, IN ACCORDANCE WITH THE  
APPROVED MINING PLAN.

Provisions of act, regulations or permit violated

UMC 771.19  
UMC 817.124

Portion of operation to which notice applies

SOUTHERN PORTION OF PROPERTY ABOVE  
MINE SITE WHERE PREVIOUS SUBSIDENCE  
HAS OCCURRED.

Remedial action required (including any interim steps)

FILL & COVER TENSION CRACKS OR CONSTRUCT  
THE NECESSARY STRUCTURES TO PREVENT  
ACCESS INTO AREA.

Abatement time (including interim steps)

COMPLETE THE WORK BY OCTOBER 28,  
1988.