3-13-90

0003

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

7/00

inspection report

Permit No. INA/015/002

Inspection Date Oct 10, 1989

Permittee/Operator Name Western States Chemicals

Business Address 4975 Van Gordon Street

City Wheat Ridge State Colo Zip 80033

Mine D.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Bam & Ingrid Blomberg / Jim Blackburn

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection _____ Weather conditions Clear / Warm

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☒	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 10/10/89

Please number comments to correspond with topics on previous page.

General Comments. Sam Blomberg and his daughter accompanied the undersigned on this inspection. Also, Jim Blackburn who does on site work was also present. In General the recent work performed by Blackburn held up well.

Other Sediment Control. The operator had placed additional wings on several silt fences. Some of the other silt fences need wings in order to avoid end running. These were pointed out to Mr. Blackburn.

Revegetation. Mr. Blomberg pointed out the vegetal transects together with highlighting the results of his study. He is of the opinion that revegetation density, composition, etc. will be able to meet the performance standards. We visited the reference area.

Subsidence. We made a field check of the subsidence survey area. No subsidence cracks were observed. The operator had previously filled the cracks and seeded the redisturbed area.

Copy of report mailed to WSM/Sam Blomberg. SLC Fax: OSM/Brian Smith/DOGM-Joe Helfrich

Copy of report ~~given to~~ filed PFG

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/13/89

DOGM IR-2

an equal opportunity employer

11 86 001049