7-27-89 7100.

0009

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 5, 1989
.1 hour

Permittee and/or Operators Name: Western States Minerals Corporation
Business Address: 26050 E Jamison Circle Aurora CO 80016
Mine Name: J.B. King Permit Number: INA/015/002
Type of Mining Activity: Underground ____ Surface ____ Other ____
County: Emery
Company Official (s): ____
State Official(s): Joe Helfrich, Rade Orell, Tom Emmett
Partial: XX Complete: ____ Date of Last Inspection: June 8, 1989
Weather Conditions: Clear and Sunny
Acreage: Permitted ____ Disturbed ____ Regraded ____ Seeded ____ Bonded ____
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

jb
MN85/14

an equal opportunity employer

INSPECTION REPORT
(continuation sheet)

DATE OF INSPECTION July 5, 1989

On July 5, 1989, an aerial inspection of this site was conducted by the referenced State and Federal officials. No violations were observed.

Photographs (slides), were taken and are available at the Division of Oil, Gas and Mining, Salt Lake Office as well as the Office of Surface Mining, Albuquerque Field Office.

Copy of this Report:
Mailed/filed to: John Kathmann (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature Joe Helfrich Date: July 27, 1989

jb
MN47/43